



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 25486



WO #: 25486

Customer: 47602 - TRIAM RV CENTER-EAST TN  
 Address: 1202 IDELL ROAD  
 BULLS GAP, TN  
 37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11116

Stock Desc: 2025 TT KZ-RV CONNECT 301BHKSE

Model: 301BHKSE

Serial #: 4EZTL3123S4046065

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 21 MAY 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 27 MAY 25

Warr. Date:

**Job #1 - Warranty**

COMPLAINT: INTERIOR DOOR TO THE BATHROOM IS VERY HARD TO CLOSE AND OPEN

CAUSE: NOTED ON DAF

CORRECTION: DOOR HINGE NEEDS TO BE RELOCATED JUST A SMALL BIT SO THE DOOR WILL OPEN AND CLOSE CORRECTLY.

LABOR .30

**Labor**

Job #	Description	Hours	Total
1	ADJUSTED DOOR HINGE	0.30	52.50
<b>Subtotal for Job #1:</b>			<b>52.50</b>

**Job #2 - Warranty**

COMPLAINT: SEAM TAPE ABOVE BATHROOM DOOR ON BOTH SIDES OF THE DOOR IS COMING LOOSE AND BUBBLING OUT

CAUSE: NOTED ON DAF

CORRECTION: TAKE HEAT GUN AND LAY SEAM TAPE DOWN FLAT

LABOR .20

**Labor**

Job #	Description	Hours	Total
2	CORRECTED SEAM TAPE	0.10	17.50
<b>Subtotal for Job #2:</b>			<b>17.50</b>

**Job #3 - Warranty**

COMPLAINT: FASCIA ON INTERIOR SLIDE HAS SEVERAL NAIL HOLES AND CHIPS.

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND THE AREA.

LABOR .20

**Labor**

Job #	Description	Hours	Total
3	COLOR AND FILLED AREA	0.10	17.50

Customer #: 47602  
 TRI-AM RV CENTER-EAST  
 TN,



Subtotal for Job #3: 17.50

W/O: 25486

**Job #4 - Warranty**

COMPLAINT: THE SECOND DRAWER DOWN IN THE KITCHEN AT STOVE AREA GOES IN ON ONE SIDE AND NOT THE OTHER. DRAWER IS VERY LOOSE AND WIGGLES WHEN PULLING DRAWER OUT.

CAUSE: NOTED ON DAF.

CORRECTION: REMOVE DRAWER AND GUIDES, LINE GUIDES UP CORRECTLY AND REINSTALL GUIDE.

LABOR .20

**Labor**

Job #	Description	Hours	Total
4	ADJUSTED	0.30	52.50

Subtotal for Job #4: 52.50

**Job #5 - Warranty**

COMPLAINT: ENTERTAINMENT CABINET HAS NAIL HOLES AND SCRATCHES.

CAUSE: NOTED ON DAF.

CORRECTION: FILL,COLOR AND BLEND AREA

LABOR .20

**Labor**

Job #	Description	Hours	Total
5	COLOR AND FILLED	0.10	17.50

Subtotal for Job #5: 17.50

**Job #6 - Warranty**

COMPLAINT: PAINT ON KITCHEN BENCH STILE WAS NOT PAINTED ALL THE WAY.SPOTS COMING UP THRU THE BLACK PAINT.

CAUSE: NOTED ON DAF.

CORRECTION: COLOR AND BLEND THE AREA.

LABOR .20

**Labor**

Job #	Description	Hours	Total
6	STAINED AND BLENDED	0.10	17.50

Subtotal for Job #6: 17.50

Parts Total: 0.00  
 Labour Total: 175.00  
 Sublet Total: 0.00  
 Extras Total: 0.00

**WORK ORDER TOTAL: 175.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,



Customer Signature : \_\_\_\_\_

Date: 27 May 2025

W/O: 25486

# Customer Work Order



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

