



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 25537 BOWMAN-DUFF,
DINAH



Estimate: 25537 (Appointment Date: 31 MAY 2025 - Time: 11:00am)

Customer: 92717 - BOWMAN-DUFF, DINAH
Address: PO BOX 342
TALBOTT, TN
37877

Home Phone: 423-312-9558

Work Phone:

Author: CHL

Location: IH

Invoice #:

Stock #:
Stock Desc: 2011 A FOREST RIVER GEORGE
TOWN
Model:
Serial #: 1F66F5DY9B0A08870
Chassis #:
Mileage: 23964
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 31 MAY 25
Promise Date: 30 JUN 25
Promise Time: 09:00am
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

COMPLAINT: CHANGE OIL

CORRECTION: OIL AND FILTER CHANGED

Labor

Code	Description	Hours	Rate	Total
Z990	LOF	0	175.00	0.00

Parts

Part #	Description	Qty	Price	Total
75150	SAE 5W20	0	7.99	0.00
1372	OIL FILTER	0	16.99	0.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

COMPLAINT: CHANGE AIR FILTER

CORRECTION: REPLACED AIR FILTER

Labor

Code	Description	Hours	Rate	Total
Z990	AIR FILTER	0	175.00	0.00

Parts

Part #	Description	Qty	Price	Total
9136	AIR FILTER	0	45.99	0.00

Subtotal for Job #2: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____



Subtotal for Job #ROOFINS: 0.00

Job #4 - External

CS THAT THERE IS A WATER LEAK COMING FROM UNDER THE KITCHEN CABINETS CHECK A/C LOCATION IS WHERE THE TV IS AT

Subtotal for Job #4: 0.00

Job #5 - External

USA EXT WAR

Subtotal for Job #5: 0.00

Job #6 - External

COMPLAINT: CS THE THAT THE JACKS ARE MAKING NOISES WHEN GOING UP AND DOWN CHECK AND ADVISE UNIT IS NOT LEVELING

CAUSE: JACKS NEED LUBED

Subtotal for Job #6: 0.00

Job #3 - External

COMPLAINT: CS THAT THE FRONT BATHROOM TOILET WONT HOLD WATER CHECK AND ADVISE

CAUSE: NEEDS TOILET SEAL

Subtotal for Job #3: 0.00

Job #7 - External

COMPLAINT: INSTALL SCREEN DOOR COVER FOR HANDLE(SLIDING PLASITC COVER)

CORRECTION: INSTALLED SCREEN DOOR COVER

Labor

Code	Description	Hours	Rate	Total
Z990	INSTALL	0	175.00	0.00

Parts

Part #	Description	Qty	Price	Total
31-7913	SCREEN DOOR SLIDE E SERIES	0	18.99	0.00

Subtotal for Job #7: 0.00

Job #8 - External

COMPLAINT: INSTALL DOOR HOLDER PARTS PULLED DOOR HIS AWNING WHEN OPENED MAYBE ADD A BUMPER

CORRECTION: INSTALLED DOOR STOP

Labor

Code	Description	Hours	Rate	Total
Z990	INSTALL	0	175.00	0.00

Parts

Part #	Description	Qty	Price	Total
JR10695	DOOR BUMPER BLACK	0	5.99	0.00

Subtotal for Job #8: 0.00

Job #9 - External

COMPLAINT: CHECK CABLE IN COACH HAVE TO RUN A CABLE INTO COACH FROM POLE TO GET CABLE

CAUSE: FOUND THAT THE CABLE LINE HAS A SHORT



Subtotal for Job #9: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 05 Jun 2025

Customer
Estimate

