



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25547



WO #: 25547

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11121

Stock Desc: 2025 TT KZ-RV CONNECT SE

241BHKSE

Model: 241BHKSE

Serial #: 4EZTL2629S4046526

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 02 AUG 25

Date In: 02 JUN 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 25 AUG 25

Warr. Date: 02 AUG 25

Job #1 - Warranty

COMPLAINT: DOOR/ WALL TRIM IN THE BATHROOM HAS HOLES AND DAMAGE

CAUSE: NOTED ON DAF

CORRECTION: SEVERAL PLACES NEED TO BE FILLED, COLORED AND BLENDED
LABOR .30

Labor

Job #	Description	Hours	Total
1	FILL AND COLOR	0.10	17.50
Subtotal for Job #1:			17.50

Job #2 - Warranty

COMPLAINT: MED CABINET IN THE BATHROOM PAINT IS SCRATCHED OFF.

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA
LABOR .20

Labor

Job #	Description	Hours	Total
2	COLOR AND BLEND	0.10	17.50

Parts

Part #	Description	Qty	Price	Total
166287	DOOR,CABINET,FLAT PANEL,SQUARE,SANDGRAU MATTE,.708X12-3/4X29	1.00	45.97	45.97

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	16.60	16.60

Subtotal for Job #2: 80.07

Job #3 - Warranty

COMPLAINT: KITCHEN PANTRY WALL HAS NAIL/STAPLE HOLES.

CAUSE: NOTED ON DAF.

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



CORRECTION: COLOR, FILL AND BLEND THE AREA. THIS IS MULTIPLE PLACES.
LABOR .30

Labor			
Job #	Description	Hours	Total
3	COLOR AND FILL	0.10	17.50
Subtotal for Job #3:			17.50

Job #4 - Warranty

COMPLAINT: THE STILE AT THE KITCHEN SEATING IS FADED IN COLOR IN SPOTS.

CAUSE: NOTED ON DAF.

CORRECTION: TECH NEEDS TO REMOVE THE STILE TO PAINT EVENLY, THEN REINSTALL.
LABOR .30

Labor			
Job #	Description	Hours	Total
4	REPAIT AND INSTALL	0.10	17.50
Subtotal for Job #4:			17.50

Job #5 - Warranty

COMPLAINT: KITCHEN SEAT CUSHION HAS A HOLE ON THE TOP CORNER.

CAUSE: NOTED ON DAF.

CORRECTION: REPLACE THE CUSHION.
LABOR .10

Labor			
Job #	Description	Hours	Total
5	REPLACED COVER	0.10	17.50

Parts				
Part #	Description	Qty	Price	Total
479096	DINETTE SEAT COVER, U37, 2025, 23X37, CONNECT, BLAKE DOLPHIN FABRIC	1.00	25.52	25.52
Subtotal for Job #5:				43.02

Job #6 - Warranty

COMPLAINT: STILE AT THE TOP, BOTTOM AND SIDE OF TV IS SCRATCHED.

CAUSE: NOTED ON DAF.

CORRECTION: FILL,COLOR AND BLEND AREA.
LABOR .30

Labor			
Job #	Description	Hours	Total
6	FILL AND COLOR	0.10	17.50
Subtotal for Job #6:			17.50

Job #7 - Warranty

COMPLAINT: CABINET DOOR AND STILE LEFT OF FIREPLACE HAS FADED PAINT AND BLACK MARKS.

CAUSE: NOTED ON DAF.

CORRECTION: CLEAN,COLOR AND BLEND AREA.
LABOR .20

W/O: 25547



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Labor

Job #	Description	Hours	Total
7	FILL AND COLOR	0.10	17.50

Subtotal for Job #7: 17.50**Job #8 - Warranty**

COMPLAINT: WOOD VALANCE RIGHT OF BED HAS CHIP IN THE BOARD.

CAUSE: NOTED ON DAF.

CORRECTION: FILL, COLOR AND BLEND AREAS.

LABOR .20

Labor

Job #	Description	Hours	Total
8	FILL AND COLOR	0.10	17.50

Subtotal for Job #8: 17.50**Job #9 - Warranty**

COMPLAINT: RIGHT INSIDE THE ENTRY DOOR A CABINET DOOR IS BUBBLED OUT.

CAUSE: NOTED ON DAF.

CORRECTION: REPLACE THE CABINET DOOR.

LABOR .30

Labor

Job #	Description	Hours	Total
9	REPLACED CABINET DOOR	0.30	52.50

Subtotal for Job #9: 52.50

Parts Total: 71.49

Labour Total: 192.50

Sublet Total: 0.00

Extras Total: 16.60

WORK ORDER TOTAL: 280.59

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 25 Aug 2025

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,