



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25547



WO #: 25547

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11121

Stock Desc: 2025 TT KZ-RV CONNECT SE

241BHKSE

Model: 241BHKSE

Serial #: 4EZTL2629S4046526

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 02 JUN 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: DOOR/ WALL TRIM IN THE BATHROOM HAS HOLES AND DAMAGE

CAUSE: NOTED ON DAF

CORRECTION: SEVERAL PLACES NEED TO BE FILLED, COLORED AND BLENDED
LABOR .30

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: MED CABINET IN THE BATHROOM PAINT IS SCRATCHED OFF.

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: KITCHEN PANTRY WALL HAS NAIL/STAPLE HOLES.

CAUSE: NOTED ON DAF.

CORRECTION: COLOR, FILL AND BLEND THE AREA. THIS IS MULTIPLE PLACES.
LABOR .30

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: THE STILE AT THE KITCHEN SEATING IS FADED IN COLOR IN SPOTS.

CAUSE: NOTED ON DAF.

CORRECTION: TECH NEEDS TO REMOVE THE STILE TO PAINT EVENLY, THEN REINSTALL.
LABOR .30

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00**Job #5 - Warranty**

COMPLAINT: KITCHEN SEAT CUSHION HAS A HOLE ON THE TOP CORNER.

CAUSE: NOTED ON DAF.

CORRECTION: REPLACE THE CUSHION.

LABOR .10

Subtotal for Job #5: 0.00**Job #6 - Warranty**

COMPLAINT: STILE AT THE TOP, BOTTOM AND SIDE OF TV IS SCRATCHED.

CAUSE: NOTED ON DAF.

CORRECTION: FILL,COLOR AND BLEND AREA.

LABOR .30

Subtotal for Job #6: 0.00**Job #7 - Warranty**

COMPLAINT: CABINET DOOR AND STILE LEFT OF FIREPLACE HAS FADED PAINT AND BLACK MARKS.

CAUSE: NOTED ON DAF.

CORRECTION: CLEAN,COLOR AND BLEND AREA.

LABOR .20

Subtotal for Job #7: 0.00**Job #8 - Warranty**

COMPLAINT: WOOD VALANCE RIGHT OF BED HAS CHIP IN THE BOARD.

CAUSE: NOTED ON DAF.

CORRECTION: FILL, COLOR AND BLEND AREAS.

LABOR .20

Subtotal for Job #8: 0.00**Job #9 - Warranty**

COMPLAINT: RIGHT INSIDE THE ENTRY DOOR A CABINET DOOR IS BUBBLED OUT.

CAUSE: NOTED ON DAF.

CORRECTION: REPLACE THE CABINET DOOR.

LABOR .30

Subtotal for Job #9: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

W/O: 25547

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 04 Jun 2025

Customer Signature : _____

Customer Work
Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

