

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Paid
 CLAIM 2324984
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4FSAS28RJ046573
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 003 / 003A
 ITEM # SAF4003MB
 DEALER RO # 25554
 CLAIM START DATE 06/06/2025
 CLAIM END DATE 06/14/2025

Labor rate: \$165.00

OWNER INFORMATION

RANDY RENNER
 285 STONE DAM RD
 Chuckey, TN 37641
 USA

Retail Date of Purchase 11/02/2024

WARRANTY EXPIRATION DATE 11/02/2025

Claim Line Details

Labor

Line# 1	Operation Code 10-12-01-11-001401	Operational Description Slide Out Control Module - Frame & Chassis/Slide Out System - Lippert/Replace/ Electrical
---------	--------------------------------------	---

Complaint, Cause, Correction

Original Note : ashlee@dealer-advisors.com, 2025-06-06 09:23:38 :: Complaint: Bed slide not running out Cause: Bed slide controller is not putting power out to the motor, so the slide will work as designed to Correction: Replace the slide out room control

Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$165.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$82.50

Notes

Part

Line# 1	Item # F100464990	Description SLIDE OUT, CONTROL FOR IN-WALL CABLE 10800160 *REPLACES VPN 10800090*
---------	----------------------	---

Model #	Serial #	Part tag	0000369950
Sub Qty 1.00	Sub Dlr Price \$135.80	Sub Freight	\$18.50
Appr Qty 1.00	Appr Dlr Price \$135.80	Appr Freight	\$18.50

Notes

Submitted

Labor Amt	\$165.00
Parts & Freight	\$154.30
Total	\$319.30

Approved

Labor Amt	\$82.50
Parts & Freight	\$154.30
Total	\$236.80

DEALER _____ DATE _____
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE

All repairs described have been inspected and are satisfactory.