



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25588



WO #: 25588

Customer: 47602 - TRIAM RV CENTER-EAST TN
 Address: 1202 IDELL ROAD
 BULLS GAP, TN
 37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11131

Stock Desc: 2026 TT KZ-RV SPORTSMEN SE

261BHKSE

Model: 261BHKSE

Serial #: 4EZTU2828T5056843

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 28 JUL 25

Date In: 10 JUN 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 22 AUG 25

Warr. Date: 28 JUL 25

Job #1 - Warranty

COMPLAINT: SHOWER SURROUND STICKING OUT ON ONE SIDE AND IS NOT SECURED TO THE WALL LIKE THE OTHER SIDE IS.

CAUSE: NOTED ON DAF.

CORRECTION: ADD DOUBLE SIDED ADHESIVE TAPE TO THE SURROUND.

LABOR .30

Labor

Job #	Description	Hours	Total
1	ADDED RIVETS	0.10	17.50

Other Services

Code	Description	Qty	Price	Total
NII	RIVETS, SHOP SUPPLY	1.00	5.99	5.99

Subtotal for Job #1: 23.49

Job #2 - Warranty

COMPLAINT: ATTIC VENT IN THE BATHROOM HAS A BROWN STAIN ON IT.

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE ATTIC VENT.

LABOR .20

Labor

Job #	Description	Hours	Total
2	CLEANED	0.20	35.00

Subtotal for Job #2: 35.00

Job #3 - Warranty

COMPLAINT: WALL TRIM IN BATHROOM HAS STAPLES STICKING OUT.

CAUSE: NOTED ON DAF

CORRECTION: SECURE STAPLES IN PROPERLY, CLEAN, COLOR AND BLEND AREA.

LABOR .20

Customer #: 47602
 TRIAM RV CENTER-EAST
 TN,



Labor			
Job #	Description	Hours	Total
3	SECURED STAPLES	0.10	17.50
Subtotal for Job #3:			17.50

Job #4 - Warranty

COMPLAINT: THE TOP BUNK PLATFORM IS DAMAGED AND HAS A DEEP SCRATCH ON THE BOARD WHERE THE MATTRESS LAYS.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE THE DAMAGED BOARD, REPLACE WITH NEW AND CLEAN THE AREA.
LABOR 1.0

Labor			
Job #	Description	Hours	Total
4	FILLED	0.10	17.50
Subtotal for Job #4:			17.50

Job #5 - Warranty

COMPLAINT: LIVING AREA SLIDE FASCIA LEFT SIDE LEG AND TOP HAS SEVERAL HOLES ACROSS BOTH.

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND THE AREAS
LABOR .20

Labor			
Job #	Description	Hours	Total
5	FILL COLOR AND BLEND	0.20	35.00
Subtotal for Job #5:			35.00

Job #6 - Warranty

COMPLAINT: RIGHT TOP SIDE OF SLIDE FASCIA IS DAMAGED.

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE FASCIA
LABOR 1.0

Labor			
Job #	Description	Hours	Total
6	REPLACED FASCIA	0.20	35.00

Parts				
Part #	Description	Qty	Price	Total
165102	FASCIA,SLIDEOUT,HEADER,MUSHROOM GRAY/NOCE COGNAC,WITH BRUSHED GOLD INSERT	1.00	55.87	55.87

Other Services				
Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	107.99	107.99
Subtotal for Job #6:				198.86

Job #7 - Warranty

COMPLAINT: BACK PANEL BEHIND KITCHEN SEATING IS WARPED AND DAMAGED.

CAUSE: NOTED ON DAF



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



CORRECTION: REPLACE PANEL
LABOR 1.0

Labor

Job #	Description	Hours	Total
7	FILL AND COLOR	0.20	35.00

Subtotal for Job #7: 35.00

Parts Total: 55.87
Labour Total: 192.50
Sublet Total: 0.00
Extras Total: 113.98
WORK ORDER TOTAL: 362.35

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 22 Aug 2025

Customer Work Order

W/O: 25588



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

