

KZRV, L.P.
0985 N 900 W
SHIPSHEWANA, IN 46565
260-768-4016
driversheets@kz-rv.com

Dealer: TRI-AM RV CENTER OF EAST

Model 2026 Sportsmen SE 261BHKSE

TENNESSEE, INC.

Run# 551252

1202 IDELL ROAD

Serial# 4EZTU2828T5056843

BULLS GAP, TN 37711 USA

Invoice# IT5056843

Invoice Date 5/22/2025

SO # 0000646165

PO# TN051925-56843

Retail Sold

DRIVER INSTRUCTIONS:

1. Verify the serial numbers to be certain the invoiced unit and shipped unit are the same
2. Torque the lug nuts
3. Check the unit to assure there is neither exterior nor interior damage
4. Verify that all keys are in the unit
5. Assure any identified damages have been repaired before taking the unit

I have completed the above items and all is satisfactory.

On behalf of the dealer with which I have/my firm has contracted to deliver the unit referenced hereon, I hereby affirm that I have taken possession of the unit and accept all risk of loss effective the date signed below.

Howard Johnson
Driver

M.D.Z
Transport Company Name

6/3/25
Date

I hereby certify that I am not an employee or otherwise a legal representative of the dealership by which I or my firm has been hired to transport the RV referenced on this form.

DEALER INSTRUCTIONS

Check the unit for damage and items that are invoiced but not on the unit. Any discrepancies must be listed and verified by the driver, as the driver is responsible for damage incurred, and for items which are not on the unit when he accepted it from the plant and not on it when you receive it. If you have none, **PLEASE WRITE NONE.**

SHORTAGES

DAMAGES

No Driver Damage

Check Refer Door ☒

Power Cord in Unit ☒

Dealer Sign Tonga England

Date 6-4-25

Power Cord in Unit YES

Driver Sign H. Johnson

Date 6/3/25

K-Z CHECK IN FORM

DATE: 6-9

TECH: SP

STOCK# 11131

26

56843

Sportsmen

261BHKSE

YEAR

VIN

BRAND

MODEL

ITEMS TO BE CORRECTED:

- ① Shower Surround not secure & sticking out.
- ② Attic Vent in Bathroom is stained.
- ③ Wall trim in Bathroom has a staple sticking out
- ④ Bed (^{top}Bunk) platform has a deep cut in it.
- ⑤ living slide fascia top (L) & (R) leg nail/staple holes
- ⑥ (R) top slide fascia damaged
- ⑦ Back panel behind kitchen seating is Warped and damaged.