



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 25588



WO #: 25588

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:  
Author: S.DAVIS  
Location: IH  
Invoice #:

Stock #: 11131  
Stock Desc: 2026 TT KZ-RV SPORTSMEN SE  
261BHKSE  
Model: 261BHKSE  
Serial #: 4EZTU2828T5056843  
Chassis #:  
Mileage: 0  
Key #:  
Req'n #:  
License #:  
Trim:

Purchase Date:  
Date In: 10 JUN 25  
Promise Date:  
Promise Time:  
Schedule Date:  
Completed:  
Warr. Date:

**Job #1 - Warranty**

COMPLAINT: SHOWER SURROUND STICKING OUT ON ONE SIDE AND IS NOT SECURED TO THE WALL LIKE THE OTHER SIDE IS.

CAUSE: NOTED ON DAF.

CORRECTION: ADD DOUBLE SIDED ADHESIVE TAPE TO THE SURROUND.  
LABOR .30

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: ATTIC VENT IN THE BATHROOM HAS A BROWN STAIN ON IT.

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE ATTIC VENT.  
LABOR .20

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: WALL TRIM IN BATHROOM HAS STAPLES STICKING OUT.

CAUSE: NOTED ON DAF

CORRECTION: SECURE STAPLES IN PROPERLY, CLEAN, COLOR AND BLEND AREA.  
LABOR .20

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: THE TOP BUNK PLATFORM IS DAMAGED AND HAS A DEEP SCRATCH ON THE BOARD WHERE THE MATTRESS LAYS.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE THE DAMAGED BOARD, REPLACE WITH NEW AND CLEAN THE AREA.  
LABOR 1.0

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



Subtotal for Job #4: 0.00

**Job #5 - Warranty**

COMPLAINT: LIVING AREA SLIDE FASCIA LEFT SIDE LEG AND TOP HAS SEVERAL HOLES ACROSS BOTH.

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND THE AREAS  
LABOR .20

Subtotal for Job #5: 0.00

**Job #6 - Warranty**

COMPLAINT: RIGHT TOP SIDE OF SLIDE FASCIA IS DAMAGED.

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE FASCIA  
LABOR 1.0

Subtotal for Job #6: 0.00

**Job #7 - Warranty**

COMPLAINT: BACK PANEL BEHIND KITCHEN SEATING IS WARPED AND DAMAGED.

CAUSE: NOTED ON DAF

CORRECTION: REPLACE PANEL  
LABOR 1.0

Subtotal for Job #7: 0.00

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

-----  
MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 10 Jun 2025

Customer Signature : \_\_\_\_\_

W/O: 25588



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

