

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Paid
 CLAIM 2333933
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TRLB2XSD461344
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 010 / 010B
 ITEM # RLT2513S
 DEALER RO # 25611
 CLAIM START DATE 06/13/2025
 CLAIM END DATE 06/25/2025

Labor rate: \$165.00

OWNER INFORMATION

BRET CAMPBELL
 156 LINK RD
 Cottontown, TN 37048
 USA

Retail Date of Purchase 03/07/2025 WARRANTY EXPIRATION DATE 03/07/2026

Claim Line Details

Labor

Line# 1	Operation Code 40-115-01-11-001362	Operational Description WFCO 8900 Series Converter Motherboard - Lower Section, Charger - Electrical/ Converter (WFCO)/Replace/Electrical
---------	---------------------------------------	---

Complaint, Cause, Correction

Original Note : ashlee@dealer-advisors.com, 2025-06-13 20:50:01 :: Complaint: Converter issues with the unit
 Cause: Connected to shore power the unit has no 12 VDC. Converter has a good source going to it, however no
 output from converter. All fuses checked out to be good. Correction: Faulty converter, replace converter and test

Model#	WF-8955-AD-WAGO	Dlr Sub Hrs	1.00	Sub Labor Amt	\$165.00
Serial#	AC04W243602861	Appr Hrs	1.00	Appr Labor Amt	\$165.00

Notes

Hello, typically the lower board only needs replaced for this converter. upon your
 acknowledgment i will authorize the lower board and update the repair code. kerb
 Hello, typically the lower board only needs replaced for this converter. upon your
 acknowledgment i will authorize the lower board and update the repair code. kerb
 That will work, thank you!
 authorized to replace, please return the defective. Thank you.

Part

Line# 1	Item # F100332530	Description CONVERTER PART - SOP CONVERTER PART - SOP: AUTO DETECT LOWER CHARGING SECTION, 55 AMP - V# WF-8955-AD-MBA			
	Model #	Serial #	Part tag	0000371490	
	Sub Qty	1.00	Sub Dlr Price	\$231.92	Sub Freight \$18.50
	Appr Qty	1.00	Appr Dlr Price	\$231.00	Appr Freight \$19.42

Notes

Labor

Line# 2	Operation Code 40-196-24-11-001297	Operational Description Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
---------	---------------------------------------	--

Complaint, Cause, Correction

Original Note : ashlee@dealer-advisors.com, 2025-06-13 20:52:02 :: Complaint: NO 12 VDC from battery Cause:
 Tested battery voltage and it is good. Traced wiring, found short to ground on battery pos wire and several other
 12v wires pinched Correction: Remove and reinstall underbelly to gain access to wiring to remove from rail

Model#	Dlr Sub Hrs	5.00	Sub Labor Amt	\$825.00
Serial#	Appr Hrs	4.00	Appr Labor Amt	\$660.00

Notes

Hello, the labor time submitted to Forest River has been reviewed and reduced based on the
 photos and description provided as well as the most applicable flat rate repair code. kerb

Submitted	Labor Amt	\$990.00
	Parts & Freight	\$250.42
	Total	\$1,240.42

Approved	Labor Amt	\$825.00
	Parts & Freight	\$250.42
	Total	\$1,075.42

DEALER _____ **DATE**

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE**

SIGNATURE

All repairs described have been inspected and are satisfactory.