

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Paid
 CLAIM 2335616
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TRLL24SZ194381
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 010 / 010D
 ITEM # RLT2906BS
 DEALER RO # 25614
 CLAIM START DATE 06/16/2025
 CLAIM END DATE 08/14/2025

Labor rate: \$165.00

OWNER INFORMATION

CHARLES CLINE
 1537 LAKEVIEW CIRCLE
 Morristown, TN 37814
 USA

Retail Date of Purchase 06/13/2025

WARRANTY EXPIRATION DATE

06/13/2026

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 60-137-01-00-001511 Thetford Toilet Ball Valve - Plumbing/Toilet (Thetford)/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-06-16 14:33:08 :: Complaint: Thetford toilet foot pedal is sticking and will not close, toilet holding water also Cause: Inner toilet bowl seal is hard and not sealing, allowing water to leak out and valve not to close properly Correction: Remove & replace toilet seal
Model# 42070 **Dlr Sub Hrs** 0.70 **Sub Labor Amt** \$115.50
Serial# E107ABVS00084 **Appr Hrs** 0.70 **Appr Labor Amt** \$115.50

Notes

We have updated the repair code to a more appropriate one based on the identified root cause of this repair request

Part

Line# 1 **Item #** **Description**
 F100361316 TOILET PART - SOP: WASTE BALL SEAL - V# 42141
Model # **Serial #** **Part tag**
Sub Qty 1.00 **Sub Dlr Price** \$19.57 **Sub Freight** \$0.00
Appr Qty 1.00 **Appr Dlr Price** \$19.57 **Appr Freight** \$0.00

Notes

Line# 2 **Item #** **Description**
 F100068715 TOILET PART - SOP: CLOSET BOLT PACKAGE - V# 42115 | 10C
Model # **Serial #** **Part tag**
Sub Qty 1.00 **Sub Dlr Price** \$14.43 **Sub Freight** \$0.00
Appr Qty 1.00 **Appr Dlr Price** \$14.43 **Appr Freight** \$0.00

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 30-101-01-00-001076 Hinged Passage Door - Interior/Interior Doors/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-06-16 14:34:44 :: Complaint: Bathroom door has a bubble Cause: Material on the door has developed bubbles Correction: Remove and replace bathroom door
Model# **Dlr Sub Hrs** 0.50 **Sub Labor Amt** \$82.50
Serial# **Appr Hrs** 0.50 **Appr Labor Amt** \$82.50

Notes

bvdillon

Part
Line# 1

Item #
F100604979

Description
DOOR - PFL: LAV PASSAGE DOOR, SHAKER STYLE - ANDOVER SABLE - 23
3/4" X 74" - V# 615118

Model #
Sub Qty 1.00
Appr Qty 1.00

Serial #
Sub Dlr Price \$130.82
Appr Dlr Price \$130.82

Part tag
Sub Freight \$116.65
Appr Freight \$116.65

Notes

Submitted Labor Amt \$198.00
Parts & Freight \$281.47
Total \$479.47

Approved Labor Amt \$198.00
Parts & Freight \$281.47
Total \$479.47

DEALER _____ **DATE** _____

SIGNATURE
I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER _____ **DATE** _____

SIGNATURE
All repairs described have been inspected and are satisfactory.