



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25616



WO #: 25616

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11090
Stock Desc: 2025 THFW FOREST RIVER ROGUE
341GS
Model: 341GS
Serial #: 4X4FVGK23S5403456
Chassis #:
Mileage:0
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 18 JUL 25
Date In: 14 JUN 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date: 18 JUL 25

Job #1 - Warranty

COMPLAINT: NDS COMPARTMENT DOOR SCRATCHED IN 3 PLACES

CAUSE: NOTED ON DAF

CORRECTION: REPLACE COMPARTMENT DOOR AND RESEAL THE AREA
LABOR 1.0

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: COMPARTMENT AREA BLACK TRAY IS DAMAGED AND SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: SCRAP OFF SEALANT, REMOVE AND REPLACE TRAY THEN RESEAL AREA
LABOR 1.5

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: ENTRY DOOR STEPS HAVE A SCRATCH AT THE TOP, AS SOON AS YOU WOULD WALK IN UNIT.

CAUSE: NOTED ON DAF

CORRECTION: PAINT AND BLEND THE AREA
LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: FRIDGE DOOR SCRATCHED IN TWO PLACES

CAUSE: NOTED ON DAF

CORRECTION: REPLACE FRIDGE DOOR
LABOR .50

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: ONE OF THE KITCHEN CABINET DOORS ARE LOWER THAN THE OTHER

CAUSE: NOTED ON DAF

CORRECTION: ADJUST CABINET DOOR
LABOR .10

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: SPOTS ON THE KITCHEN WALL WERE FILLED AT FACTORY AND NOT CLEANED AND BLENDED

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND BLEND SPOT TO EVEN IT OUT
LABOR .10

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: BLACK SPOT ON BEDROOM WALL AT THE DOOR

CAUSE: NOTED ON DAF

CORRECTION: CLEAN MARK THEN COLOR AND BLEND TO MATCH
LABOR .20

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: BEDROOM DOOR IS SCRATCHED AND HAS A CHIP

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND BOTH AREAS
LABOR .20

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: BEDROOM DOOR WILL NOT SLIDE TO OPEN AND CLOSE CORRECTLY.

CAUSE: NOTED ON DAF
DOOR HANGS BELOW HANGER

CORRECTION: REMOVE HARDWARE THAT HOLDS DOOR AND REINSTALL IN CORRECT PLACE TO ALLOW DOOR TO OPERATE CORRECTLY.
LABOR .30

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: STAINS ON THE CABINET DOORS IN THE PATIO AREA

CAUSE: NOTED ON DAF

CORRECTION: CLEAN, COLOR FILL AND BLEND THE AREA



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



LABOR .20

Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: COUNTER TOP IN REAR AREA OF TYHE UNIT IS SCRATCHED IN 3 PLACES

CAUSE: NOTED ON DAF

CORRECTION: BUFF AND CLEAN THE COUNTER TOPS
LABOR 2.0

Subtotal for Job #11: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 16 Jul 2025

W/O: 25616



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

