



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25629



WO #: 25629

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11118

Stock Desc: 2025 DT FOREST RIVER SANDPIPER
40DUPLEX

Model: 40DUPLEX

Serial #: 4X4TSAS24SJ048328

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 19 JUN 25

Date In: 17 JUN 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 19 JUN 25

Job #1 - Warranty

COMPLAINT: KITCHEN DRAWER AT SINK RUBS AND WILL NOT CLOSE

CAUSE: NOTED ON DAF

CORRECTION: ADJUST KICHEN DRAWER GUIDE SO DRAWER WILL OPERATE CORRECTLY.
LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: REAR ENTRY DOOR WILL NOT SHUT WITH THE STEPS DOWN

CAUSE: NOTED ON DAF

CORRECTION: REAR ENTRY STEPS NEED TO BE ADJUSTED SO DOOR CAN CLOSE PROPERLY
LABOR .30

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: SINK IN REAR BATH HAS EXCESSIVE AMOUNT OF SEALANT AROUND THE BOWL.
THIS MAKES THE SINK LOOK STAINED AROUND THE EDGES.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE EXTRA SEALANT AND CLEAN AREA
LABOR .30

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: REAR BATH INTERIOR DOOR HAS SMALL HOLE ON DOOR AND TRIM

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND AREAS
LABOR .20

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: BEDROOM SLIDE FASCIA AND SQUARE ENDS HAVE HOLES FROM FACTORY.

CAUSE: NOTED ON DAF

CORRECTION: SMOOTH, FILL, COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: DRAWER GUIDE IN THE BEDROOM ON THE RIGHT SIDE IS DAMAGED AND NOT ALLOWING THE DRAWER TO OPERATE CORRECT.

CAUSE: NOTED ON DAF

CORRECTION: REPLACE DRAWER GUIDE
LABOR .30

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: PANTRY DOOR IN LIVING/KITCHEN AREA HAS A DEEP SCRATCH AND PAINT CHIPPED IN ANOTHER PLACE.

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR, SMOOTH AND BLEND THE AREA
LABOR .20

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: BLACK STILE AROUND THE TV AREA IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA TO MATCH
LABOR .10

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: KITCHEN SLIDE FASCIA HAS HOLES AND A BLACK STAIN

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND HOLES AND CLEAN OFF BLACK STAIN
LABOR .20

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: BLACK MARKS ON WALL IN BATHROOM OVER TOILET

CAUSE: NOTED ON DAF

CORRECTION: CLEAN OFF MARKS AND COLOR WALL TO MATCH IF NEEDED
LABOR .20Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Subtotal for Job #10: 0.00**Job #11 - Warranty**

COMPLAINT: SHADE IN THE BEDROOM GOES UP SIDEWAYS AND WILL NOT GO UP ALL THE WAY

CAUSE: NOTED ON DAF

CORRECTION: ADJUST SHADE
LABOR .30**Subtotal for Job #11: 0.00****Job #12 - Warranty**

COMPLAINT: CEILING PANEL IN BEDROOM HAS A HOLE NEXT TO THE LIGHT

CAUSE: NOTED ON DAF

CORRECTION: REMOVE DAMAGED CEILING PANEL AND REPLACE WITH NEW
LABOR**Subtotal for Job #12: 0.00****Job #13 - Warranty**

COMPLAINT: BLACK STAIN ON WALL IN KITCHEN

CAUSE: NOTED ON DAF

CORRECTION: CLEAN MARKS OFF THE WALL AND COLOR TO BLEND IF NEEDED
LABOR .10**Subtotal for Job #13: 0.00****Job #14 - Warranty**

COMPLAINT: PAINT HAS FADED ON THE RAIL AT THE SECOND LOFT AREA

CAUSE: NOTED ON DAF

CORRECTION: PAINT AND BLEND THE AREA ON THE RAILS
LABOR .20**Subtotal for Job #14: 0.00****Job #15 - Warranty**

COMPLAINT: MIDDLE BEDROOM DOOR HAS A CHIP ON THE SIDE

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND CLEAN THE AREA
LABOR .20**Subtotal for Job #15: 0.00****Job #16 - Warranty**COMPLAINT: SEALANT ON THE WALL ON FIRST LOFT SEALANT HAS GAPS AND VOIDS. THIS
MAKES IT LOOK LIKE THE WALL IS CRACKED

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND RESEAL THE AREA
LABOR .10Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Subtotal for Job #16: 0.00

W/O: 25629

Job #17 - Warranty

COMPLAINT: TOP WALL AT STEPS HAS BLACK MARKS AND MAKES WALL LOOK STAINED

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREA
LABOR .10

Subtotal for Job #17: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 17 Jun 2025

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,