



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 24517
Promised Date:
20 OCT 24



WO #: 24517

Customer: 66766 - RAY, MICHAEL
Address: 3 SOUTH FOXXBOROUGH LANE
JOHNSON CITY, TN
37604

Home Phone: (423) 791-1264

Work Phone:

Author: CHL

Location: IH

Invoice #: 416397

Stock #: 10379

Stock Desc: 2021 FW FOREST RIVER

SANDPIPER 321RL

Model: 321RL

Serial #: 4X4FSAH20MJ041903

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 05 FEB 22

Date In: 27 SEP 24

Promise Date: 30 OCT 24

Promise Time: 09:00am

Schedule Date:

Completed: 11 DEC 24

Warr. Date: 05 FEB 22

Job #1 - External

COMPLAINT: CS THAT THE TOILET IS STILL CLOGGING UP WHEN USING IT

CORRECTION: SNAKED AND PLUNGED DOWN PIPE TO BLACK TANK FOUND A BALL OF TP

Subtotal for Job #1: 0.00

Job #2 - External

COMPLAINT: CS THAT THE SLIDE TOPPERS ARE PULLING AWAY FROM THE CAMPER

CAUSE: FOUND THAT THE SLIDE TOPPERS ARE LOCKING UP CAUSING THE FABRIC TO BE TO TIGHT

CORRECTION: REPLACED SLIDE TOPPERS AND TESTED

Labor

Job #	Description	Hours	Total
2	REPAIR	4.50	N/C

Parts

Part #	Description	Qty	Price	Total
00-0484	SOLERA SLIDE OUT AWNING 84" FITS ROOM WIDTH 74" TO 79 3/4" BLACK VINYL BLACK HARDWARE	1.00	N/C	N/C
00-0495	Awning; Solera Slide Topper	1.00	N/C	N/C
00-0494	12FT SLIDER-12FT BLACK-W HRDWRE-BLACK V000168328	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - External

REPAIR REAR FIBERGLASS AND MOLDING DAMAGE ON DRIVERS SIDE

Labor

Job #	Description	Hours	Total
3	REPAIR FIBERGLASS AND MOLDING	4.50	787.50

Parts

Part #	Description	Qty	Price	Total
20-6982	021-85202-16 LONG LEG CORNER MOLDING 16'	1.00	75.59	75.59
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	12.59	12.59
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	12.59	12.59

Customer #: 66766
RAY, MICHAEL



W/O: 24517
Promised Date: 30 OCT 24



Customer #: 66766
RAY, MICHAEL



Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	50.00	50.00

Subtotal for Job #3: 938.27

Job #WINT3 - External

COMPLAINT: WINTERIZE-FW/ CLASS A/ DESTINATION TRAILER/ DEISEL

Due to the winterization process, most refrigerator filters and water filters will need to be replaced. Because of the variability of filters, customers will be responsible for ordering/supplying the replacement filter for your unit at time of dewinterization in the spring.

Because of the number of different filters being used by manufacturers, Tri-Am RV cannot guarantee that we will have the correct filter in stock at time of the appt. Therefore, we recommend that you either pre-order your filters, or bring them with you at your appointment time.

Initial/Date: _____

CORRECTION: WINTERIZE COMPLETE NO LEAKS FOUND AT THIS TIME

Labor

Job #	Description	Hours	Total
WINT3	WINTERIZE FRESH WATER SYSTEM	1.30	227.50

Parts

Part #	Description	Qty	Price	Total
13-1639	ANTIFREEZE -50	3.00	7.19	21.57

Subtotal for Job #WINT3: 249.07

Parts Total: 122.34
Labour Total: 1,015.00
Sublet Total: 0.00
Extras Total: 50.00
Tax Total: 115.76
Deductible: 34.00

WORK ORDER TOTAL: 1,337.10

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 03 Jul 2025

