



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 25672



WO #: 25672

Customer: 47602 - TRIAM RV CENTER-EAST TN  
 Address: 1202 IDELL ROAD  
 BULLS GAP, TN  
 37711

Home Phone: 423-235-1167

Work Phone:  
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11142  
 Stock Desc: 2026 TT DUTCHMEN ASPEN TRAIL  
 MINI 17BH  
 Model: 17BH  
 Serial #: 4YDTATG1XT8920098  
 Chassis #:  
 Mileage:0  
 Key #:  
 Req'n #:  
 License #:  
 Trim:

Purchase Date:  
 Date In: 25 JUN 25  
 Promise Date:  
 Promise Time:  
 Schedule Date:  
 Completed: 06 AUG 25  
 Warr. Date:

**Job #1 - Warranty**

COMPLAINT: SCRATCHED METAL ON NDS OF THE UNIT, DAMAGE IS ALL DOWN THE SIDE OF THIS UNIT ON THE METAL

CAUSE: DAMAGED WHEN INSTALLED  
 NOTED ON DAF

CORRECTION: REPLACE THE DAMAGED METAL  
 REMOVE AND REPLACE THE DAMAGED METAL  
 LABOR 10.0

**Labor**

Job #	Description	Hours	Total
1	REPLACED DAMAGED METAL	10.00	1,750.00

**Parts**

Part #	Description	Qty	Price	Total
731359	SIDING 12"X 360 BLACK	1.00	120.04	120.04
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	10.26	10.26

**Other Services**

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	888.80	888.80
CRA	CRATE CHARGES	1.00	50.00	50.00

**Subtotal for Job #1: 2,819.10**

**Job #2 - Warranty**

COMPLAINT: METAL IS SCRATCHED AND DAMAGED ON THE BACK OF THE UNIT

CAUSE: DONE AT FACTORY, NOTED ON DAF

CORRECTION: REMOVE AND REPLACE DAMAGED METAL ON THE BACK OF THE UNIT  
 LABOR 4.0

**Labor**

Job #	Description	Hours	Total
2	REPLACED METAL	4.00	700.00

**Parts**

Part #	Description	Qty	Price	Total
733692	SIDING POLAR WHIT 16"X PER FT	9.00	3.73	33.57
430415	5.5"X120" 90*	1.00	21.63	21.63
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	10.26	10.26

Customer #: 47602  
 TRI-AM RV CENTER-EAST  
 TN,



**Other Services**

Code	Description	Qty	Price	Total
CRA	CRATE CHARGES	1.00	50.00	50.00
SHP	SHIPPING/FREIGHT FEE	1.00	195.57	195.57

**Subtotal for Job #2: 1,011.03**

**Job #3 - Warranty**

COMPLAINT: SIDE PANEL OF THE KITCHEN SEATING HAS PAINT RUBBED OFF

CAUSE: NOTED ON DAF

CORRECTION: COLOR, BLEND AND CLEAN AREA  
LABOR .20

**Labor**

Job #	Description	Hours	Total
3	COLOR AND BLEND AREA	0.20	35.00

**Subtotal for Job #3: 35.00**

**Job #4 - Warranty**

COMPLAINT: WHEN YOU RETRACK THE AWING IT WILL EXTEND

CAUSE: SWITCH INSTALLED BACKWARDS TO THE LABELS  
NOTED ON THE DAF

CORRECTION: INSTALL SWITCH TO CORRECT POSITION  
LABOR .20

**Labor**

Job #	Description	Hours	Total
4	INSTALL SWITCH TO CORRECT POSITION	0.20	35.00

**Subtotal for Job #4: 35.00**

**Job #5 - Warranty**

COMPLAINT: FURNACE IS IN SIDEWAYS AND THE COVER IS CROOKED

CAUSE: INSTALLED SIDEWAYS AT THE FACTORY  
NOTED ON DAF

CORRECTION: REMOVE COVER AND FURNACE, REINSTALL CORRECTLY  
LABOR 1.0

**Labor**

Job #	Description	Hours	Total
5	REINSTALL FURNACE COVER CORRECTLY	0.30	52.50

**Subtotal for Job #5: 52.50**

**Job #6 - Warranty**

COMPLAINT: SMALL HOLE IN WALL AT THE BATHROOM DOOR

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND CLEAN AREA  
LABOR .10

**Labor**

Job #	Description	Hours	Total
6	FILL AND COLOR	0.20	35.00



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,



Subtotal for Job #6: 35.00

W/O: 25672

Parts Total:	195.76
Labour Total:	2,607.50
Sublet Total:	0.00
Extras Total:	1,184.37
<b>WORK ORDER TOTAL:</b>	<b>3,987.63</b>

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 06 Aug 2025

Customer Work Order



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

