

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0049080	CLAIM STATUS	Paid
TRI AM RV CENTER OF EAST TN		CLAIM	2349597
1202 IDELL ROAD (I-81 EXIT 23)		CLAIM ORIGIN	WEB
BULLS GAP, TN 37711		ORIGINAL CLAIM ID	
USA		VIN	4X4MFRG24RF064929
		CHASSIS VIN	1FDXE4FN2SDD01919
		MILEAGE	6999
Labor rate:	\$165.00	SITE/WAREHOUSE	034 / 034A
OWNER INFORMATION		ITEM #	FRC3051SF
JANET WILLIS		DEALER RO #	25684
1845 BAYS MOUNTAIN RD		CLAIM START DATE	06/27/2025
New Market, TN 37820		CLAIM END DATE	06/30/2025
USA			
Retail Date of Purchase	04/12/2025	WARRANTY EXPIRATION DATE	04/12/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-49-01-00-000579	Front Fiberglass Cap - Exterior/Front, Fiberglass Cap, Cab Over/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : ashlee@dealer-advisors.com, 2025-06-27 14:24:41 :: Complaint: On claim 2260080, we agreed to allow fat cat customers to come and replace the rock guard on the forester. We were told to put in for the time our bay was used to do the replacement Cause: Bay had to be used for the R&R of the rock guard on top cap and hood Correction: Bay time for the repairs			
Model#		Dlr Sub Hrs	2.00	Sub Labor Amt \$330.00
Serial#		Appr Hrs	2.00	Appr Labor Amt \$330.00
	Notes			
	VCB for bay use.			
	whats wrong, with the rock guard ?			
	please submit pictures of the damages			
	Please refer to C2260080, all of that info is on there. Thank you!			

Submitted	Labor Amt	\$330.00	Approved	Labor Amt	\$330.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$330.00		Total	\$330.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.