



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25721



WO #: 25721

Customer: 60689 - BUCKNER, MALCOLM
Address: 252 EASTER GAP RD
MARSHALL, NC
28753
Home Phone: 828-206-0952
Work Phone:
Author: SPD
Location: IH
Invoice #:

Stock #: 10908
Stock Desc: 2024 TT KZ-RV CONNECT SE
312BHKSE
Model: 312BHKSE
Serial #: 4EZTL3325R4120335
Chassis #:
Mileage:
Key #: 2500
Req'n #:
License #:
Trim:

Purchase Date: 06 FEB 25
Date In: 07 JUL 25
Promise Date:
Promise Time:
Schedule Date:
Completed: 23 JUL 25
Warr. Date: 06 FEB 25

Job #1 - Warranty

COMPLAINT: CS OUTSIDE STOVE TOP IS LIGHTING BUT NOT HEATING WELL

CAUSE: TESTED LP PRESSURE AT QUICK CONNECT, NO ISSUES WERE DETECTED AT THIS TIME.
TURNED ON STOVE AND MEASURED AT TEMP WITHIN 10 MINS AND IT WAS 503 DEGREES. TECH
CAN NOT DUPLICATE ISSUE AT THIS TIME.

CORRECTION: NO ISSUE FOUND AT THIS TIME.

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CS VINYL INSERT ON SLIDE OUT IS COMING APART

CAUSE: VINYL INSERT HAS SPLIT AND CRACKED ON BOTH SLIDE OUTS.

CORRECTION: REMOVE AND REPLACE VINYL INSERT ON TOP SECTIONS OF BOTH SLIDER
ROOMS
LABOR .40

Labor

Job #	Description	Hours	Total
2	REPLACE VINYL INSERT	0.40	70.00

Parts

Part #	Description	Qty	Price	Total
JR10015	VINYL INSERT 25' BLACK	1.00	15.99	15.99

Subtotal for Job #2: 85.99

Parts Total:	15.99
Labour Total:	70.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	85.99

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 60689
BUCKNER, MALCOLM



Customer Signature : _____

Date: 23 Jul 2025

W/O: 25721



Customer #: 60689
BUCKNER, MALCOLM



Customer Work
Order

