



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25732
Promised Date:



Customer #: 91325
MUSE, PATRICK



WO #: 25732 (Appointment Date: 09 JUL 2025 - Time: 09:00am)

Customer: 91325 - MUSE, PATRICK
Address: 373 TRIMONT TRAIL APT 5
FRANKLIN, NC
28734

Home Phone: 828-371-5461

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 10922

Stock Desc: 2024 TT KZ-RV CONNECT 302FBK

Model: 302FBK

Serial #: 4EZTL3222R4030335

Chassis #:

Mileage: 0

Key #: 9690

Req'n #:

License #:

Trim:

Purchase Date: 10 DEC 24

Date In: 09 JUL 25

Promise Date: 30 JUL 25

Promise Time: 09:00am

Schedule Date:

Completed: 21 AUG 25

Warr. Date: 10 DEC 24

Job #1 - Warranty

AWNING WILL NOT ROLL UP WHEN RAINING NOW THE REAR ARM HAS COME APART

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: FRONT JACK NOT WORKING

CAUSE: TECH FOUND THE OPERATION ON THE LOWER SIDE OF SWITCH IS NOT WORKING

CORRECTION: REPLACE SWITCH ON JACK

LABOR .50

Labor

Job #	Description	Hours	Total
2	REPLACED JACK SWITCH	0.30	52.50

Parts

Part #	Description	Qty	Price	Total
142319	SWITCH,UP/DOWN,POWER TONGUE JACK,FOR MODEL #77122-R,RAM	1.00	6.90	6.90

Subtotal for Job #2: 59.40

Job #3 - Warranty

COMPLAINT: CS THAT THE ENTRY HANDLE IS STARTING TO COME APART

CAUSE: FOAM ON ENTRY HANDLE HAS CRACKED AND IS COMING OFF

CORRECTION: REPLACE THE FOAM ON ENTRY DOOR HANDLE

LABOR .10

Labor

Job #	Description	Hours	Total
3	REPLACED HANDLE	0.10	17.50

Parts

Part #	Description	Qty	Price	Total
31-1531	REPLACEMENT FOAM TUBE GRIP	1.00	9.33	9.33

Subtotal for Job #3: 26.83

Job #4 - Warranty

COMPLAINT: CS THAT TRIM IS STARTING TO POP LOOSE BY THE COUCH AT THE FLOOR



W/O: 25732
Promised Date: 30 JUL 25



Customer #: 91325
MUSE, PATRICK



CAUSE: THE STAPLES USED TO BUILD THE WALL WHERE THE TRIM IS ARE NOT HOLDING. THIS IS ALLOWING THE WALL TO PULL AWAY AND THE TRIM POPPING OFF.

CORRECTION: REMOVE FASCIA AND PARTIAL WALL PANEL, RESECURE WALL USING SCREWS AND SECURE TRIM BACK INTO CORRECT PLACE.

LABOR 2.0

Labor

Job #	Description	Hours	Total
4	RESECURED TRIM PROPERLY	2.00	350.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #4: 350.00

Job #5 - Warranty

CS THAT THE LARGE SLIDE ,SLIDE TOPPER IS LOOSE AND SAGGING

Subtotal for Job #5: 0.00

Parts Total: 16.23
Labour Total: 420.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 436.23

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 21 Aug 2025

