



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25791



WO #: 25791

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11113

Stock Desc: 2025 TT KZ-RV SPORTSMEN CLASS

191BHK

Model: 191BHK

Serial #: 4EZTK1811S5046256

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 22 JUL 25

Date In: 18 JUL 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 28 JUL 25

Warr. Date: 22 JUL 25

Job #1 - Warranty

COMPLAINT: NEGATIVE WIRE FOR BATTERY MISSING

CAUSE: NOTED ON DAF

CORRECTION: REPLACE NEGATIVE WIRE

LABOR .50

Labor

Job #	Description	Hours	Total
1	REPLACED NEGATIVE WIRE	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
19-1190	PRIMARY WIRE, 4 GAUGE, BLK	1.50	2.09	3.14

Subtotal for Job #1: 90.64

Job #2 - Warranty

COMPLAINT: STILE ON BUNK BED HAS A SPOT

CAUSE: NOTED ON DAF

CORRECTION: CLEAN, COLOR AND BLEND AREA

LABOR .20

Labor

Job #	Description	Hours	Total
2	CLEAN AND BLENDED	0.20	35.00

Subtotal for Job #2: 35.00

Job #3 - Warranty

COMPLAINT: BATHROOM DOOR HAS A CHIP ON IN

CAUSE: NOTED ON DAF

CORRECTION: REPLACE BATHROOM DOOR

LABOR .50

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Labor			
Job #	Description	Hours	Total
3	REPAIRED AREA	0.30	52.50

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES FOR COLOR STICK AND MATERIALS TO REPAIR	1.00	6.99	6.99

Subtotal for Job #3: 59.49**Job #4 - Warranty**

COMPLAINT: BATHROOM MED CABINET HAS SPOTS OF PAINT CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

Labor			
Job #	Description	Hours	Total
4	COLOR AND BLENDED	0.20	35.00

Subtotal for Job #4: 35.00**Job #5 - Warranty**

COMPLAINT: PAINT CHIP ON CORNER STILE NEXT TO FRIDGE

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA

LABOR .20

Labor			
Job #	Description	Hours	Total
5	COLOR AND BLENDED	0.20	35.00

Subtotal for Job #5: 35.00**Job #6 - Warranty**

COMPLAINT: WALL LUAN NEXT TO THE FRIDGE IS SPOTTED AND HAS SEVERAL NAIL HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREAS

LABOR .30

Labor			
Job #	Description	Hours	Total
6	FILL AND COLOR	0.30	52.50

Subtotal for Job #6: 52.50**Job #7 - Warranty**

COMPLAINT: INT SLIDE FASCIA AND LEGS HAVE NAIL AND STAPLE HOLES IN SEVERAL DIFF PLACES

CAUSE: NOTED ON THE DAF

CORRECTION: FILL, COLOR AND CLEAN THE AREA

LABOR .20

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Labor

Job #	Description	Hours	Total
7	FILL AND COLOR	0.20	35.00

Subtotal for Job #7: 35.00

Job #8 - Warranty

COMPLAINT: THE PANEL TO THE LEFT OF THE ENTRY DOOR HAS PAINT SMUDGES AND NAIL HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND THE AREAS
LABOR .30

Labor

Job #	Description	Hours	Total
8	FILL AND COLOR	0.30	52.50

Subtotal for Job #8: 52.50

Parts Total: 3.14

Labour Total: 385.00

Sublet Total: 0.00

Extras Total: 6.99

WORK ORDER TOTAL: 395.13

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 28 Jul 2025

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,