



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25810



WO #: 25810

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11128

Stock Desc: 2026 TT KZ-RV CONNECT 313MK

Model: 313MK

Serial #: 4EZTL3326T4056880

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 23 JUL 25

Date In: 21 JUL 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 28 JUL 25

Warr. Date: 23 JUL 25

Job #1 - Warranty

COMPLAINT: CEILING PANEL IN LIVING ROOM IS STAINED

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND AREA

LABOR .30

Labor

Job #	Description	Hours	Total
1	CLEANED	0.10	17.50

Subtotal for Job #1: 17.50

Job #2 - Warranty

COMPLAINT: NDS SLIDE FASCIA HAS NAIL HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

KZ DENIED THIS LINE

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: WINDOW STILE NEXT TO RECLINER HAS SEVERAL HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA

KZ DENIED THIS LINE

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: BLACK STILE AT THE KITCHEN SEAT IS FADED IN THREE DIFFERENT SPOTS

CAUSE: NOTED ON DAF

CORRECTION: PAINT AND BEND THE STILE TO MATCH EVENLY

LABOR .30

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Labor

Job #	Description	Hours	Total
4	REPAIRED AREA	0.10	17.50

Subtotal for Job #4: 17.50**Job #5 - Warranty**

COMPLAINT: STILE OVER THE FRIDGE HAS WHITE SPOTS ON IT, PAINT LOOKS FADED

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND STILE TO MATCH AND EVEN PAINT

LABOR .20

Labor

Job #	Description	Hours	Total
5	COLOR AND BLEND	0.10	17.50

Subtotal for Job #5: 17.50**Job #6 - Warranty**

COMPLAINT: STILE ST KITCHN SEATING IS STICKING OUT AT THE TOP

CAUSE: NOTED ON DAF

CORRECTION: REMOVE THE STILE AND RESECURE BACK IN PLACE CORRECTLY

LABOR .50

Labor

Job #	Description	Hours	Total
6	MISC. LABOR CODEREMOVED AND RESECURE BACK IN PLACE	0.50	87.50

Subtotal for Job #6: 87.50**Job #7 - Warranty**

COMPLAINT: BEDROOM DOOR HAS A STICKY SPOT AND PAINT FADED

CAUSE: NOTED ON DAF

CORRECTION: CLEAN SPOT, COLOR AND BLEND AREAS

LABOR .30

Labor

Job #	Description	Hours	Total
7	CLENAED AND BLENDED	0.10	17.50

Subtotal for Job #7: 17.50**Job #8 - Warranty**

COMPLAINT: BEDROOM ENTRY STILE HAS NAIL HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

Labor

Job #	Description	Hours	Total
8	MISC. LABOR CODE	0.30	52.50

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

Subtotal for Job #8: 52.50

Job #9 - Warranty

COMPLAINT: BOTTOM DRAWER IN BEDROOM WILL NOT CLOSE WITHOUT FORCE

CAUSE: NOTED ON DAF

CORRECTION: DRAWER GUIDE NEEDS TO BE REMOVED AND REINSTALLED INTO THE CORRECT PLACE

LABOR .50

Labor

Job #	Description	Hours	Total
9	REINSTALLED CORRECTLY	0.30	52.50

Subtotal for Job #9: 52.50

Job #10 - Warranty

COMPLAINT: CLOSET DOOR CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

Labor

Job #	Description	Hours	Total
10	COLOR AND BLENDED	0.10	17.50

Subtotal for Job #10: 17.50

Job #11 - Warranty

COMPLAINT: DS COMPARTMENT DOOR RING BLACK MARKS

CAUSE: NOTED ON DAF

CORRECTION: CLEAN, COLOR AND BLEND AREA

CLAIM IS DENIED

Subtotal for Job #11: 0.00

Job #12 - Warranty

COMPLAINT: ENTRY DOOR HIT FRAME ON THE RIGHT SIDE WHEN PUTTING UP

CAUSE: NOTED ON DAF

CORRECTION: ENTRY DOOR STEPS NEED TO BE ADJUSTED

LABOR .50

Labor

Job #	Description	Hours	Total
12	ADJUST ENTRY DOOR	0.30	52.50

Subtotal for Job #12: 52.50

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

W/O: 25810

Parts Total:	0.00
Labour Total:	332.50
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	332.50

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 28 Jul 2025

Customer Signature : _____

Customer Work
Order



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

