



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25860
 Promised Date:



WO #: 25860

Customer: 92509 - GUTHRIE, JOHN
 Address: 1202 IDELL RD
 BULLS GAP, TN
 37711

Home Phone: 415-720-2055

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10953

Stock Desc: 2025 TT KZ-RV SPORTSMEN CLASS
 181BH

Model: 181BH

Serial #: 4EZTK1811S4041273

Chassis #:

Mileage:0

Key #: 5090

Req'n #:

License #:

Trim:

Purchase Date: 25 APR 25

Date In: 01 AUG 25

Promise Date: 01 AUG 25

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 25 APR 25

Job #1 - Warranty

COMPLAINT: CS THAT THE CO2 DETECTOR IS BEEPING AND WONT STOP

CAUSE: FOUND THAT THE CO2 DETECTOR HAS FAILED INTERNALY HAS GOOD POWER AND
 GROUND BUT WONT STOP BEEPING EVERY COUPLE SEC

CORRECTION: REPLACED CO2 DETECTOR
 LABOR .30

Parts

Part #	Description	Qty	Price	Total
15-2155	Carbon Monoxide/ Propane Leak Detector; Detects Both LP And CO Gas B;ACK	1.00	72.19	72.19

Subtotal for Job #1: 72.19

Parts Total: 72.19
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 72.19

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 92509
 GUTHRIE, JOHN



Customer Signature : _____

Date: 13 Aug 2025

