



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25868



WO #: 25868

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11171

Stock Desc: 2026 THFW FOREST RIVER ROGUE
341GS11

Model: 341GS11

Serial #: 4X4FVGK26T5403615

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 02 AUG 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 26 AUG 25

Warr. Date:

Job #1 - Warranty

COMPLAINT: BROWN SPOTS ON PATIO WALL AT THE BAR

CAUSE: NOTED ON DAF

CORRECTION: CLEAN SPOTS AND COLOR BLEND TO MATCH WALL

LABOR .20

Labor

Job #	Description	Hours	Total
1	CLEANED SPOTS AND COLOR BLENDED	0.20	33.00
Subtotal for Job #1:			33.00

Job #2 - Warranty

COMPLAINT: HOLES IN THE MOLDING STRIPS ON TOP ABOVE WINDOW IN THE BAR/KITCHEN AREA

CAUSE: NOTED ON DAF

CORRECTION: FILL HOLES, COLOR AND BLEND

LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THE LIGHTS ON THE RIGHT SIDE (STANDING LOOKING AT IT) OF THE RECLINER SEATING WILL NOT TURN OFF.

CAUSE: NOTED ON DAF

CORRECTION: SEATING IS NOT WORKING AS DESIGNED TO, REPLACE THE RIGHT SIDE OF THE SEATING.

LABOR .50

Labor

Job #	Description	Hours	Total
3	REPLACED CUP HOLDER	0.40	66.00

Parts

Part #	Description	Qty	Price	Total
785445	CUP HOLDER	1.00	103.13	103.13

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	9.39	9.39

Subtotal for Job #3: 178.52

Parts Total: 103.13
Labour Total: 99.00
Sublet Total: 0.00
Extras Total: 9.39

WORK ORDER TOTAL: 211.52

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 26 Aug 2025

W/O: 25868



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

