



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 25885 REED, ELIZABETH



Estimate: 25885

Customer: 87425 - REED, ELIZABETH
Address: 2620 CARPENTERS CHAPEL RD
MOSHEIM, TN
37818

Home Phone: (423) 972-1137

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 11090

Stock Desc: 2025 THFW FOREST RIVER ROGUE
341GS

Model: 341GS

Serial #: 4X4FVGK23S5403456

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 18 JUL 25

Date In: 05 AUG 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 18 JUL 25

Job #1 - Warranty

COMPLAINT: SLIDE OUT WITH FIREPLACE HAS NO POWER IN ANY OF THE OUTLET

CAUSE: DUE TO FACTORY DEFECT THE MOLEX CONNECTOR GOING TO SLIDE IS FAULTY

CORRECTION: REMOVE FOAM UNDERBELLY BRING OUT 110 WIRES REPLACE MOLEX FOR SLIDE
ROOM REINSTALL WIRES AND FOAM

LABOR 1.0

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: LP DETECTOR WIRED BACKWARDS

CAUSE: DURING INSTALLATION FACTORY INSTALLED 12VDC HOT TO GROUND AND GROUND TO
HOT

CORRECTION: REWIRE DETECTOR

LABOR .3

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: GFCI OUTLETS NOT WORKING

CAUSE: ON BACK OF GFI TECHNICIAN FOUND A LOOSE NUETRAL WIRE

CORRECTION: REMOVE GFI OUTLET REINSTALL NUETRAL WIRE

LABOR .5



Subtotal for Job #3: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
Tax Total: 0.00
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 05 Aug 2025

Customer Estimate

