

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080		CLAIM STATUS Paid	
TRI AM RV CENTER OF EAST TN		CLAIM 2397701	
1202 IDELL ROAD (I-81 EXIT 23)		CLAIM ORIGIN WEB	
BULLS GAP, TN 37711		ORIGINAL CLAIM ID	
USA		VIN 5ZT2RSHC1S3035655	
		CHASSIS VIN	
		MILEAGE 0	
Labor rate:	\$165.00	SITE/WAREHOUSE 010 / 010G	
OWNER INFORMATION		ITEM # RLTG19FD	
DONALD ELLIOTT		DEALER RO # 25912	
104 CALLOWAY RD E		CLAIM START DATE 08/11/2025	
Pineville, KY 40977		CLAIM END DATE 08/20/2025	
USA			
Retail Date of Purchase 06/28/2025		WARRANTY EXPIRATION DATE 06/28/2026	

Claim Line Details

Labor					
Line# 1	Operation Code 30-92-01-00-003956		Operational Description RV Safe CO & LP Detector - Interior/Interior Miscellaneous/Replace/No Tread Code		
Complaint, Cause, Correction					
Original Note : ashlee@dealer-advisors.com, 2025-08-11 14:18:46 :: Complaint: CO and LP alarm will not stop beeping Cause: Alarm is faulty and will not shut off. LP drop test was completed and no issues found at this time Correction: Replace CO and LP alarm. Replace the alarm and perform the second LP drop test					
Model#	Dlr Sub Hrs 1.00		Sub Labor Amt \$165.00		
Serial#	Appr Hrs 0.50		Appr Labor Amt \$82.50		
Notes					

Part					
Line# 1	Item # F100170704		Description DETECTOR - PFL: LP/CARBON MONOXIDE COMBO, FLUSH MOUNT - BLACK - V# RVCOLP-2B X		
	Model #		Serial #		Part tag 0000379160
	Sub Qty 1.00		Sub Dlr Price \$39.14	Sub Freight \$18.64	
	Appr Qty 1.00		Appr Dlr Price \$39.14	Appr Freight \$18.64	
Notes					

Submitted	Labor Amt	\$165.00	Approved	Labor Amt	\$82.50
	Parts & Freight	\$57.78		Parts & Freight	\$57.78
	Total	\$222.78		Total	\$140.28

DEALER	DATE	CUSTOMER	DATE
SIGNATURE		SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.		All repairs described have been inspected and are satisfactory.	