



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25916



WO #: 25916

Customer: 92301 - BARRY, DENISE
Address: 2768 MEADOW CREST LN
SEVIERVILLE, TN
37876

Home Phone: (865) 850-1172

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11049

Stock Desc: 2025 DT KZ-RV SPORTSMEN 362DB

Model: 362DB

Serial #: 4EZTS3725S5107484

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 26 MAR 25

Date In: 13 AUG 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 26 MAR 25

Job #1 - Warranty

COMPLAINT: TOILET WILL NOT FLUSH

CORRECTION: NO WORK PREFORMED

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: WALL PAPER COMING LOOSE

CORRECTION: NO WORK PREFORMED

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: SCREEN DOOR INTO IS DAMAGED AND WILL NOT CLOSE CORRECTLY

CAUSE: SCREEN DOOR IS BOWED VERY BADLY AND COMING APART. DOOR IS FAULTY.

CORRECTION: REPLACE SCREEN DOOR
LABOR .30

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: RUST DEVELOPED ON THE FRONT WHERE YOU TOW

CAUSE: RUST DEVELOPED ON FRONT OF UNIT

CORRECTION: SAND AND PAINT THE AREA
LABOR .30

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: HOLES IN MOLDING WHERE LIGHTS ARE OVER COUCH

CORRECTION: NO WORK PREFORMED

Customer #: 92301
BARRY, DENISE



Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: GOLD STRIP IS LOOSE

CAUSE: GOLD STRIP ON SLIDE FASCIA HAS WORKED LOOSE AND FALLING OFF

CORRECTION: RESECURE STRIP BACK IN PROPER PLACE
LABOR .10

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: BACK SPLASH IN THE KITCHEN IS CHIPPING AND LEAVING HOLES

CAUSE: BACK SPLASH MATERIAL IS CHIPPING OFF

CORRECTION: REMOVE AND REPLACE BACK SPLASH
LABOR .50

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: SCREEN ON SLIDING DOOR DOES NOT CLOSE CORRECT, DENTED AND SCREWS ARE CHIPPED

CAUSE: THE SIDING ON SIDES OF THE SLIDING DOOR BOWING OUT. METAL IS NOT CUT TO FIT CORRECTLY. THIS HAS CAUSED THE DOOR TO BECOME DAMAGED AS WELL.

CORRECTION: REMOVE COMPLETE SLIDING DOOR AND TRACK, REPAIR OPENING SO THE TRACK HOUSING FITS CORRECTLY, INSTALL NEW TRACK HOUSING, NEW SCREEN DOOR AND RESEAL AREA
LABOR 3.5

Subtotal for Job #8: 0.00

Job #10 - Warranty

COMPLAINT: KITCHEN FAUCET IS LEAKING

CAUSE: FAUCET IS LEAKING AT THE BASE, FAULTY FAUCET

CORRECTION: REPLACE KITCHEN FAUCET AND TEST
LABOR .50

Subtotal for Job #10: 0.00

Job #11 - Warranty

COMPLAINT: HOLES IN THE VALANCE IN LIVING ROOM

CORRECTION: NO WORK PERFORMED

Subtotal for Job #11: 0.00

Job #12 - Warranty

HOLES VALANCE IN BEDROOM HAS HOLES

W/O: 25916



Customer #: 92301
BARRY, DENISE



Subtotal for Job #12: 0.00

Job #13 - Warranty

COMPLAINT: SLIDING DOOR SIDE LOWER METAL HAS DEVELOPED WAVES ON THEM

CAUSE: LOWER METAL IS FAULTY AND DEVELOPING WAVES, SCREWS WERE OVER TIGHTENED AT FACTORY INSTALL

CORRECTION: REMOVE ALL LOWER METAL AND TRIM THAT IS DAMAGED AND REPLACE WITH NEW. STEPS WILL NEED TO BE REMOVED AND REINSTALLED AS WELL.
LABOR 3.0

Subtotal for Job #13: 0.00

Job #14 - Warranty

COMPLAINT: WATER RUNNING DOWN FRONT OF UNIT WHERE THE RAIN GUTTERS MEET

CAUSE: THERE IS NOT THE CORRECT AMOUNT OF SEALANT IN THIS AREA ALLOWING WATER TO COME DOWN THE FRONT

CORRECTION: RESEAL AREA
LABOR .20

Subtotal for Job #14: 0.00

Job #15 - Warranty

COMPLAINT: SHOWER RUBBER CORNER SEAL IS LOOSE AND COMING OFF

CAUSE: RUBBER SEAL IS NOT STAYING IN PLACE AND TECH STATED THE SEAL WILL NOT LAY BACK IN PLACE AS DESIGNED

CORRECTION: REMOVE THE FAULTY SHOWER SEAL AND REPLACE WITH NEW SEAL
LABOR 1.0

Subtotal for Job #15: 0.00

Job #16 - Warranty

COMPLAINT: COMPARTMENT KEY LOCK IS SPINNING AND NOT ALLOWING CUSTOMER TO LOCK/UNLOCK DOOR

CAUSE: COMPARTMENT TUMBLER IS FAULTY AND WILL NOT WORK

CORRECTION: REMOVE FAULTY TUMBLER AND REPLACE WITH NEW
LABOR .30

Subtotal for Job #16: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

W/O: 25916



Customer #: 92301
BARRY, DENISE



Customer Signature : _____

Date: 18 Sep 2025

W/O: 25916

Customer Work Order



Customer #: 92301
BARRY, DENISE

