



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 25957



WO #: 25957

Customer: 47602 - TRIAM RV CENTER-EAST TN  
 Address: 1202 IDELL ROAD  
 BULLS GAP, TN  
 37711

Home Phone: 423-235-1167

Work Phone:  
 Author: S.DAVIS  
 Location: IH  
 Invoice #:

Stock #: 11176  
 Stock Desc: 2026 THTT FOREST RIVER ROGUE  
 27SUT  
 Model: 27SUT  
 Serial #: 5NHTVGE22TC005542  
 Chassis #:  
 Mileage: 0  
 Key #:  
 Req'n #:  
 License #:  
 Trim:

Purchase Date:  
 Date In: 20 AUG 25  
 Promise Date:  
 Promise Time:  
 Schedule Date:  
 Completed: 18 OCT 25  
 Warr. Date:

**Job #1 - Warranty**

COMPLAINT: SPOTS ON WALL AND CEILING IN THE SLIDE OUT

CAUSE: NOTED ON DAF

CORRECTION: SPOTS NEED TO BE BLENDED TO LOOK SMOOTH  
 LABOR .20

**Labor**

Job #	Description	Hours	Total
1	BLENDED	0.20	33.00
<b>Subtotal for Job #1:</b>			<b>33.00</b>

**Job #2 - Warranty**

COMPLAINT: TWO CABINETS IN THE KITCHEN HAVE SCRATCHES AND A CHIP ON ONE

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND THE AREA BOTH CABINETS AND SPOTS  
 LABOR .30

**Labor**

Job #	Description	Hours	Total
2	FILL AND COLOR	0.30	49.50
<b>Subtotal for Job #2:</b>			<b>49.50</b>

**Job #3 - Warranty**

COMPLAINT: THE BOTTOM OF THE BATHROOM DOOR IS ROUGH AND PAINT CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND THE AREA  
 LABOR .20

**Labor**

Job #	Description	Hours	Total
3	COLOR AND FILL	0.20	33.00

Customer #: 47602  
 TRI-AM RV CENTER-EAST  
 TN,



Subtotal for Job #3: 33.00

**Job #4 - Warranty**

COMPLAINT: KITCHEN PANTRY STILE IS CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE STILE ON PANTRY  
LABOR .50

**Labor**

Job #	Description	Hours	Total
4	REPLACED STILE	0.50	82.50

**Parts**

Part #	Description	Qty	Price	Total
F100602356	SEAM TAPE	1.00	25.74	25.74

**Other Services**

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	18.78	18.78

Subtotal for Job #4: 127.02

**Job #5 - Warranty**

COMPLAINT: STILE ON KITCHEN SLIDE IS WARPED AND STICKING OUT MORE THAN IT SHOULD

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE THE STILE ON KITCHEN SLIDE  
LABOR 1.0

**Labor**

Job #	Description	Hours	Total
5	REPLACED STILE	0.20	33.00

**Parts**

Part #	Description	Qty	Price	Total
F100645902	PANEL	1.00	54.95	54.95

**Other Services**

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	150.00	150.00

Subtotal for Job #5: 237.95

**Job #6 - Warranty**

COMPLAINT: CEILING PANEL IN BEDROOM HAS BROWN SPOTS

CAUSE: NOTED ON DAF

CORRECTION: CLEAN SPOTS AND THEN PAINT TO MATCH CEILING PANEL  
LABOR .50

**Labor**

Job #	Description	Hours	Total
6	CLEAN	0.50	82.50

Subtotal for Job #6: 82.50

**Job #7 - Warranty**

COMPLAINT: CEILING STRIP IN BEDROOM IS STAINED

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREA AND TOUCH UP PAINT IF NEEDED

W/O: 25957



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,



LABOR .20

**Labor**

Job #	Description	Hours	Total
7	CLEANED	0.10	16.50

**Subtotal for Job #7: 16.50**

Parts Total: 80.69

Labour Total: 330.00

Sublet Total: 0.00

Extras Total: 168.78

**WORK ORDER TOTAL: 579.47**

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

-----  
MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 21 Oct 2025

Customer Signature : \_\_\_\_\_

Customer Work Order

W/O: 25957



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

