



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 25958



WO #: 25958

Customer: 47602 - TRIAM RV CENTER-EAST TN  
 Address: 1202 IDELL ROAD  
 BULLS GAP, TN  
 37711

Home Phone: 423-235-1167

Work Phone:  
 Author: S.DAVIS  
 Location: IH  
 Invoice #:

Stock #: 11189  
 Stock Desc: 2026 TT DUTCHMEN ASPEN TRAIL  
 LE 29TB  
 Model: 29TB  
 Serial #: 4YDTATN26T8920207  
 Chassis #:  
 Mileage: 0  
 Key #:  
 Req'n #:  
 License #:  
 Trim:

Purchase Date:  
 Date In: 20 AUG 25  
 Promise Date:  
 Promise Time:  
 Schedule Date:  
 Completed: 24 SEP 25  
 Warr. Date:

**Job #1 - Warranty**

COMPLAINT: DUST CAP ON DRIVER SIDE REAR AXLE IS DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE DUST CAP AND CENTER INSERT  
 LABOR .50

**Labor**

Job #	Description	Hours	Total
1	REPLACE DUST CAP	0.50	87.50

**Parts**

Part #	Description	Qty	Price	Total
733433	RUBBER PLUG	1.00	0.33	0.33
733432	DUST CAP 2"	1.00	0.91	0.91

**Other Services**

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	20.64	20.64

**Subtotal for Job #1: 109.38**

**Job #2 - Warranty**

COMPLAINT: LINO FLOORING THROUGH THE LIVING AND KITCHEN AREA HAS BLACK RUBBER MARKS ACROSS IT IN SEVERAL SPOTS

CAUSE: NOTED ON DAF

CORRECTION: AREA HAVE TO BE CLEANED OFF THIS WILL NOT COME UP WITH JUST WATER  
 LABOR 1.0

**Labor**

Job #	Description	Hours	Total
2	CLEANED AREA	0.60	105.00

**Subtotal for Job #2: 105.00**

**Job #3 - Warranty**

COMPLAINT: STAIN ON BATHROOM WALL NEXT TO HANGER HOOK

CAUSE: NOTED ON DAF

Customer #: 47602  
 TRI-AM RV CENTER-EAST  
 TN,



CORRECTION: CLEAN AREA AND TOUCH UP COLOR IF NEEDED  
LABOR .20

**Labor**

Job #	Description	Hours	Total
3	CLEANED AND TOUCH UP	0.10	17.50

**Subtotal for Job #3: 17.50**

**Job #4 - Warranty**

COMPLAINT: WALL PANEL AT THE HIDDEN PANTRY IS DAMAGED.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE PANEL  
DAMAGE IS EYE LEVEL, FILL AND COLOR WILL NOT FIX ISSUE  
LABOR 2.0

**Labor**

Job #	Description	Hours	Total
4	REPLACED PANEL	1.50	262.50

**Parts**

Part #	Description	Qty	Price	Total
744994	PANEL 48"X96"	1.00	51.77	51.77

**Other Services**

Code	Description	Qty	Price	Total
CRA	CRATE CHARGES	1.00	50.00	50.00
SHP	SHIPPING/FREIGHT FEE	1.00	196.07	196.07

**Subtotal for Job #4: 560.34**

Parts Total: 53.01  
Labour Total: 472.50  
Sublet Total: 0.00  
Extras Total: 266.71  
**WORK ORDER TOTAL: 792.22**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X  
MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 24 Sep 2025

W/O: 25958



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

