



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25967



WO #: 25967

Customer: 92734 - CAGLE, ANTHONY
Address: 59 WHISPER BEND
JOHNSON CITY, TN
37604
Home Phone: (423) 804-7639
Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11088
Stock Desc: 2025 DT FOREST RIVER SANDPIPER
388JW
Model: 388JW
Serial #: 4X4TSAR26SJ048126
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 10 MAY 25
Date In: 22 AUG 25
Promise Date:
Promise Time:
Schedule Date:
Completed: 25 AUG 25
Warr. Date: 10 MAY 25

Job #1 - Warranty

COMPLAINT: HALF BATH DOOR IS HARD TO CLOSE AND OPEN, THIS IS SCRATCHING THE DOOR CATCH

CAUSE: NOTED ON DAF

CORRECTION: ADJUST DOOR HINGES, REMOVE DOOR CATCH TO PAINT
LABOR .30

Labor

Job #	Description	Hours	Total
1	ADJUSTED	0.30	49.50
Subtotal for Job #1:			49.50

Job #2 - Warranty

COMPLAINT: CEILING FAN IN THE BEDROOM MISSING SCREW

CAUSE: NOTED ON DAF

CORRECTION: REPLACE THE SCREW
LABOR .05

Labor

Job #	Description	Hours	Total
2	REPLACED SCREW	0.10	16.50
Subtotal for Job #2:			16.50

Job #3 - Warranty

COMPLAINT: THE FASCIA ON THE SLIDE IN THE LIVING AREA IS SCRATCHED AND CHIPPED.

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREAS
LABOR .30

Labor

Job #	Description	Hours	Total
3	FILL AND COLOR	0.30	49.50

Customer #: 92734
CAGLE, ANTHONY



Subtotal for Job #3: 49.50

Job #4 - Warranty

COMPLAINT: A BROWN STAIN ON THE WALL NEXT TO HIDDEN CABINET

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND TOUCH UP PAINT IF NEEDED

LABOR .20

Labor

Job #	Description	Hours	Total
4	CLENAED AND TOUCHED UP	0.20	33.00

Subtotal for Job #4: 33.00

Job #5 - Warranty

COMPLAINT: SLIDING DOOR TRACK IS BENT AND THE DOOR IS HARD TO OPEN/SHUT

CAUSE: NOTED ON DAF

CORRECTION: TECH WAS ABLE TO STRAIGHTEN THE TRACK TO ALLOW THE DOOR TO SLIDE CORRECTLY

LABOR .50

Labor

Job #	Description	Hours	Total
5	STRAIGHTEN TRACK	0.50	82.50

Subtotal for Job #5: 82.50

Job #6 - Warranty

COMPLAINT: CABINET DOOR UNDER KITCHEN FAUCET NOT CLOSING CORRECTLY AND HAS SCRATCHED PLACES ON BOTH TOPS OF THE DOORS

CAUSE: NOTED ON DAF

CORRECTION: HINGE ON CABINET DOOR NEEDS TO BE ADJUSTED TO OPERATE CORRECTLY, THEN COLOR AND BLEND SCRATCHED AREAS

LABOR .30

Labor

Job #	Description	Hours	Total
6	ADJ HINGE ON CABINET	0.30	49.50

Subtotal for Job #6: 49.50

Parts Total:	0.00
Labour Total:	280.50
Sublet Total:	0.00
Extras Total:	0.00

WORK ORDER TOTAL: 280.50

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 92734
CAGLE, ANTHONY

Customer Signature : _____

Date: 25 Aug 2025

W/O: 25967



Customer #: 92734
CAGLE, ANTHONY



Customer Work
Order

