



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 25990  
 Promised Date: 20250829



WO #: 25990 (Appointment Date: 29 AUG 2025 - Time: 09:00am)

Customer: 70521 - CANSLER, MICHAEL  
 Address: 727 HIGHTOP RD  
 MIDWAY, TN  
 37809

Home Phone: (423) 470-3369

Work Phone:  
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11060

Stock Desc: 2025 FW FOREST RIVER CEDAR

CREEK 35RL

Model: 35RL

Serial #: 4X4FCRL29SS234285

Chassis #:

Mileage: 0

Key #: 9750

Req'n #:

License #:

Trim:

Purchase Date: 15 AUG 25

Date In: 26 AUG 25

Promise Date: 30 SEP 25

Promise Time: 09:00am

Schedule Date:

Completed: 24 NOV 25

Warr. Date: 15 AUG 25

**Job #1 - External**

INSTALL COUNTER FOR CUSTOMER

**Other Services**

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C

**Subtotal for Job #1: 0.00**

**Job #2 - External**

CUSTOMER HAS SOME WARRANTY ISSUES HE WILL ADDRESS AT DROP OFF

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: CS THAT THE DOORS ON THE ISLAND ARE CROOKED

CAUSE: DOORS HAVE FALLEN DOWN AND ARE NOT EVEN

CORRECTION: ADJUST DOORS TO MAKE THEM LINE UP CORRECTLY  
 LABOR .30

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: REAR OFF DOOR SIDE SLIDE HAS A SEAL THAT IS COMING LOOSE

CAUSE: SWIPE WAS NOT INSTALLED CORRECTLY AT FACTORY. THIS HAS ALLOWED DAMAGE TO THE SWIPE AND COMING LOOSE FROM UNIT

CORRECTION: REMOVE OLD SWIPE SEAL AND REPLACE WITH NEW  
 LABOR 1.5

**Labor**

Job #	Description	Hours	Total
4	REPLACED OLD SWIPE SEAL	1.50	247.50

**Parts**

Part #	Description	Qty	Price	Total
F100606851	SLIDE SEAL	1.00	51.16	51.16

Customer #: 70521  
 CANSLER, MICHAEL





**Other Services**

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	61.73	61.73
CRA	CRATE CHARGES	1.00	5.00	5.00
<b>Subtotal for Job #4:</b>				<b>365.39</b>

**Job #5 - External**

SEE IF WE CAN ADD TV IN BASEMENT

**Subtotal for Job #5: 0.00**

**Job #6 - Warranty**

CUSTOMER NOTICED CHIP IN FROM CAP

**Subtotal for Job #6: 0.00**

**Job #7 - Warranty**

COMPLAINT: CUST STATED THERE IS A CHIP IN THE PAINT ON REAR WALL

CAUSE: REAR WALL HAS BEEN REPAIRED PRIOR AND THE FIBERGLASS FILL HAS CAME OUT

CORRECTION: REPAIR FIBER GLASS AND COLOR BLEND AREA  
 LABOR 1.0

**Labor**

Job #	Description	Hours	Total
7	REPAIRED FIBERGLASS	1.00	165.00

**Subtotal for Job #7: 165.00**

**Job #8 - Warranty**

COMPLAINT: CEDAR CREEK DECAL ON REAR IS BUBBLING UP AND CHIPPING OFF IN SPOTS

CAUSE: DECAL IS FAULTY

CORRECTION: REPLACE DECAL  
 REMOVE THE CURRENT DECAL AND REPLACE WITH NEW ONE  
 LABOR .50

**Labor**

Job #	Description	Hours	Total
8	REPLACED DECAL	0.50	82.50

**Parts**

Part #	Description	Qty	Price	Total
F100600577	REAR DECAL	1.00	34.36	34.36

**Subtotal for Job #8: 116.86**

**Job #9 - Warranty**

COMPLAINT: DECAL ON THE FRONT CAP OF THE UNIT HAS DEVELOPED A BUBBLE AND CHIPPING OFF

CAUSE: DECAL IS PEELING UP AND LEAVING A HOLE IN THE DECAL

CORRECTION: REMOVE AND REPLACE DECAL ON THE FRONT  
 LABOR .50

**Labor**

Job #	Description	Hours	Total
9	FRONT CAP PAINTED	0.50	82.50



Subtotal for Job #9: 82.50

**Job #10 - Warranty**

COMPLAINT: MIDDLE DECAL ON DS IS CHIPPING

CAUSE: DECAL IS FAULTY AND CHIPPING

CORRECTION: REMOVE AND REPLACE MIDDLE DECAL  
LABOR 1.0

**Labor**

Job #	Description	Hours	Total
10	REPLACED DECAL	0.50	82.50

**Parts**

Part #	Description	Qty	Price	Total
F100600486	DS DECAL	1.00	6.89	6.89

Subtotal for Job #10: 89.39

Parts Total: 92.41  
 Labour Total: 660.00  
 Sublet Total: 0.00  
 Extras Total: 66.73

**WORK ORDER TOTAL: 819.14**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 24 Nov 2025

Customer Signature : \_\_\_\_\_

W/O: 25990  
Promised Date: 30 SEP 25



Customer #: 70521  
CANSLER, MICHAEL

