



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25990
Promised Date:



Customer #: 70521
CANSLER, MICHAEL



WO #: 25990 (Appointment Date: 29 AUG 2025 - Time: 09:00am)

Customer: 70521 - CANSLER, MICHAEL
Address: 727 HIGHTOP RD
MIDWAY, TN
37809

Home Phone: (423) 470-3369

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11060

Stock Desc: 2025 FW FOREST RIVER CEDAR

CREEK 35RL

Model: 35RL

Serial #: 4X4FCRL29SS234285

Chassis #:

Mileage: 0

Key #: 9750

Req'n #:

License #:

Trim:

Purchase Date: 15 AUG 25

Date In: 26 AUG 25

Promise Date: 30 SEP 25

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 15 AUG 25

Job #1 - External

INSTALL COUNTER FOR CUSTOMER

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

CUSTOMER HAS SOME WARRANTY ISSUES HE WILL ADDRESS AT DROP OFF

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CS THAT THE DOORS ON THE ISLAND ARE CROOKED

CAUSE: DOORS HAVE FALLEN DOWN AND ARE NOT EVEN

CORRECTION: ADJUST DOORS TO MAKE THEM LINE UP CORRECTLY
LABOR .30

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: REAR OFF DOOR SIDE SLIDE HAS A SEAL THAT IS COMING LOOSE

CAUSE: SWIPE WAS NOT INSTALLED CORRECTLY AT FACTORY. THIS HAS ALLOWED DAMAGE TO THE SWIPE AND COMING LOOSE FROM UNIT

CORRECTION: REMOVE OLD SWIPE SEAL AND REPLACE WITH NEW
LABOR 1.5

Subtotal for Job #4: 0.00

Job #5 - External

SEE IF WE CAN ADD TV IN BASEMENT





Subtotal for Job #5: 0.00

Job #6 - Warranty

CUSTOMER NOTICED CHIP IN FROM CAP

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: CUST STATED THERE IS A CHIP IN THE PAINT ON REAR WALL

CAUSE: REAR WALL HAS BEEN REPAIRED PRIOR AND THE FIBERGLASS FILL HAS CAME OUT

CORRECTION: REPAIR FIBER GLASS AND COLOR BLEND AREA
LABOR 1.0

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: CEDAR CREEK DECAL ON REAR IS BUBBLING UP AND CHIPPING OFF IN SPOTS

CAUSE: DECAL IS FAULTY

CORRECTION: REPLACE DECAL
REMOVE THE CURRENT DECAL AND REPLACE WITH NEW ONE
LABOR .50

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: DECAL ON THE FRONT CAP OF THE UNIT HAS DEVELOPED A BUBBLE AND CHIPPING OFF

CAUSE: DECAL IS PEELING UP AND LEAVING A HOLE IN THE DECAL

CORRECTION: REMOVE AND REPLACE DECAL ON THE FRONT
LABOR .50

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: MIDDLE DECAL ON DS IS CHIPPING

CAUSE: DECAL IS FAULTY AND CHIPPING

CORRECTION: REMOVE AND REPLACE MIDDLE DECAL
LABOR 1.0

Subtotal for Job #10: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967



Customer Signature : _____

Date: 18 Sep 2025

W/O: 25990
Promised Date: 30 SEP 25



Customer #: 70521
CANSLER, MICHAEL



Customer Work
Order

