



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 26008  
 Promised Date:



WO #: 26008

Customer: 58907 - MOORE, TAMMY  
 Address: 1300 MAIN ST  
 MOSHEIM, TN  
 37818

Home Phone:  
 Work Phone: (423) 422-6685  
 Author:SPD  
 Location: IH  
 Invoice #:

Stock #: 11076  
 Stock Desc: 2025 FW FOREST RIVER CEDAR  
 CREEK 361RL  
 Model: 361RL  
 Serial #: 4X4FCRM25SS234461  
 Chassis #:  
 Mileage:0  
 Key #:  
 Req'n #:  
 License #:  
 Trim:

Purchase Date: 10 FEB 25  
 Date In: 02 SEP 25  
 Promise Date: 30 SEP 25  
 Promise Time: 09:00am  
 Schedule Date:  
 Completed: 20 OCT 25  
 Warr. Date: 10 FEB 25

**Job #1 - External**

SC TO UNIT

**Other Services**

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C

**Subtotal for Job #1: 0.00**

**Job #2 - External**

CS THAT THE ANTENNA HAS COME OFF THE ROOF CHECK AND ADVISE

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: CS THAT THE SLIDES WILL NOT COME BACK IN

CAUSE: RETRACT BUTTON WAS INOP FOR SLIDES. SLIDE WILL EXTEND, WHEN YOU RETRACT BUTTON WOULD TURN RED AND ALERT OVER CURRENT APPEARS. TECH CHECKED ALL FUSES BEFORE CONTACTING FIREFLY. KEITH WITH FIREFLY HAD TECH UNPLUG J10 PLUG AND DEADEND COACH TO RESET BOARD. WHEN PRESSING RETRACT AGAIN,TECH RECEIVED THE SAME ALERT. FIREFLY DEEMED G12 BOARD TO BE DEFECTIVE.

CORRECTION: REPLACE G12 BOARD  
 LABOR TO REPLACE G12 BOARD AND PROGRAM 1.0

**Labor**

Job #	Description	Hours	Total
3	REPLACED BOARD	1.00	165.00

**Parts**

Part #	Description	Qty	Price	Total
F100217281	G12 BOARD	1.00	407.55	407.55

**Other Services**

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	18.81	18.81

**Subtotal for Job #3: 591.36**

Customer #: 58907  
 MOORE, TAMMY



Parts Total: 407.55  
Labour Total: 165.00  
Sublet Total: 0.00  
Extras Total: 18.81  
**WORK ORDER TOTAL: 591.36**

W/O: 26008  
Promised Date: 30 SEP 25

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 20 Oct 2025

Customer Signature : \_\_\_\_\_

Customer Work  
Order



Customer #: 58907  
MOORE, TAMMY

