



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26008
Promised Date:



Customer #: 58907
MOORE, TAMMY



WO #: 26008

Customer: 58907 - MOORE, TAMMY
Address: 1300 MAIN ST
MOSHEIM, TN
37818
Home Phone:
Work Phone: (423) 422-6685
Author: CHL
Location: IH
Invoice #:

Stock #: 11076
Stock Desc: 2025 FW FOREST RIVER CEDAR
CREEK 361RL
Model: 361RL
Serial #: 4X4FCRM25SS234461
Chassis #:
Mileage: 0
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 10 FEB 25
Date In: 02 SEP 25
Promise Date: 30 SEP 25
Promise Time: 09:00am
Schedule Date:
Completed:
Warr. Date: 10 FEB 25

Job #1 - External

SC TO UNIT

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

CS THAT THE ANTENNA HAS COME OFF THE ROOF CHECK AND ADVISE

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CS THAT THE SLIDES WILL NOT COME BACK IN

CAUSE: RETRACT BUTTON WAS INOP FOR SLIDES. SLIDE WILL EXTEND, WHEN YOU RETRACT BUTTON WOULD TURN RED AND ALERT OVER CURRENT APPEARS. TECH CHECKED ALL FUSES BEFORE CONTACTING FIREFLY. KEITH WITH FIREFLY HAD TECH UNPLUG J10 PLUG AND DEADEND COACH TO RESET BOARD. WHEN PRESSING RETRACT AGAIN, TECH RECEIVED THE SAME ALERT. FIREFLY DEEMED G12 BOARD TO BE DEFECTIVE.

CORRECTION: REPLACE G12 BOARD
LABOR TO REPLACE G12 BOARD AND PROGRAM 1.3
DIAG TIME INCLUDING PHONE CALL WITH FIREFLY, LABOR .50

Subtotal for Job #3: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967



Customer Signature : _____

Date: 03 Sep 2025

W/O: 26008
Promised Date: 30 SEP 25



Customer #: 58907
MOORE, TAMMY



Customer Work
Order

