



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26033



WO #: 26033 (Appointment Date: 08 SEP 2025 - Time: 11:00am)

Customer: 93228 - LAWSON, STEWART
 Address:

Home Phone: 423-254-4315

Work Phone:
 Author: S.DAVIS
 Location: IH
 Invoice #:

Stock #:
 Stock Desc: 2025 TT FOREST RIVER VIBE T19RB
 Model: T19RB
 Serial #: 4X4TVBU24ST154048
 Chassis #:
 Mileage:
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 06 SEP 25
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed:
 Warr. Date:

Job #1 - Warranty

COMPLAINT: FRONT TONGUE JACK IS NOT WORKING. CUST HAD ISSUES WITH THIS SAME DAY IT WAS PURCHASED. HE HAS CHANGED THE FUSE AND THE JACK WORKED THEN STOPPED AGAIN AND HAS NOT WORKED SINCE.

CAUSE: 15 AMP FUSE WAS BLOWN FOR THE SECOND TIME. THIS IS NOT THE PROPER FUSE.

CORRECTION: REMOVED 15 AMP FUSE AND REPLACED WITH A 30 AMP. OPERATED SYSTEM AND FRONT TONGUE JACK IS WORKING AS DESIGNED.
 LABOR .30

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: ON DEMAND WATER HEATER IS NOT WORKING CORRECTLY AT ALL TIMES. CUSTOMER IS GETTING A E1 CODE SOMETIMES. THERE IS NO PATTERN IT WILL WORK CORRECT AND THEN JUST STOP.

CAUSE: TECH HOOKED TO WATER AND OPERATED THE WATER HEATER WITH NO ISSUES AT THIS TIME.

CORRECTION: NO ISSUES FOUND AT THIS TIME, POSS WATER PRESSURE AT PLACE CUSTOMER WAS AT.

Subtotal for Job #2: 0.00

Job #3 - External

COMPLAINT: CUS STATES SWAY BAR LOOKS BENT CHECK AND ADVISE

CORRECTION: SWAY BAR OK ASKED CUS NOT TO GREASE

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: OUTSIDE STORAGE LOCK WILL NOT TURN TO LATCH AND D-SEAL ON COMPARTMENT IS PULLING OFF

CAUSE: LOCK IS OUT OF ADJUSTMENT AND D-SEAL ON COMPARTMENT DOOR COMING APART

Customer #: 93228
 LAWSON, STEWART



CORRECTION: REMOVE CURRENT D-SEAL,REPLACE WITH NEW D-SEAL ON COMPARTMENT DOOR AND ADJSUTED LATCH
LABOR 1.0
LABOR 1.0

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: KITCHEN FAUCET IS LOOSE

CAUSE: KITCHEN FAUCET IS FAULTY AND LOOSE

CORRECTION: TECH WAS ABLE TO TIGHTEN THE FAUCET AND WORKS WITH NO LEAK
LABOR .30

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: STRAP FOR BATHROOM DOOR FASTNER CAME OFF AND CUST CAN'T LOCK DOOR IN PLACE FOR TRAVELING

CAUSE: BATHROOM DOOR STRAP CAME LOOSE AND NOT WORKING AS DESIGNED

CORRECTION: SECURE DOOR STRAP IN PROPER PLACE TO HOLD DOOR CORRECTLY IN PLACE
LABOR .20

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: PASSENGER SIDE FENDER SKIRT CRACKED BETWEEN TWO OF THE SCREWS THAT FACTORY INSTALLED

CAUSE: FENDER SKIRT WAS INSTALLED TO TIGHT AT FACTORY AND CAUSED THE SKIRT TO CRACK OVER TIME

CORRECTION: REMOVE AND REPLACE FENDER SKIRT
LABOR 1.0

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: THE PANTRY/CLOSET DOOR KNOB WORKED ITSELF LOOSE AND KNOB IS COMING OFF

CAUSE: SCREWS WORKED LOOSE AND NOT HOLDING KNOB IN PLACE CORRECT

CORRECTION: TIGHTENED UP SCREWS ON KNOB, IT IS WORKING AS DESIGNED FOR NOW
LABOR .10

Subtotal for Job #8: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00



Customer #: 93228
LAWSON, STEWART



I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 15 Sep 2025

Customer Signature : _____

W/O : 26033

Customer Work
Order



Customer #: 93228
LAWSON, STEWART

