



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 26037



WO #: 26037

Customer: 47602 - TRIAM RV CENTER-EAST TN  
 Address: 1202 IDELL ROAD  
 BULLS GAP, TN  
 37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11203  
 Stock Desc: 2026 TT FOREST RIVER  
 ROCKWOOD MINI 2511S  
 Model: 2511S  
 Serial #: 4X4TRLA29TD466795  
 Chassis #:  
 Mileage: 0  
 Key #:  
 Req'n #:  
 License #:  
 Trim:

Purchase Date:  
 Date In: 08 SEP 25  
 Promise Date:  
 Promise Time:  
 Schedule Date:  
 Completed: 23 OCT 25  
 Warr. Date:

**Job #1 - Warranty**

COMPLAINT: THE DRAWER IN BEDROOM WALL WILL NOT GOT IN CORRECT, THE GUIDE ONLY  
 ALLOWS ONE SIDE TO GO IN ALL THE WAY

CAUSE: NOTED ON DAF

CORRECTION: REMOVE DRAWER AND GUIDE, RELOCATE THE DRAWER GUIDE TO ALLOW THE  
 DRAWER TO CLOSE CORRECTLY.

LABOR .30

**Labor**

Job #	Description	Hours	Total
1	REPAIRED	0.30	49.50
<b>Subtotal for Job #1:</b>			<b>49.50</b>

**Job #2 - Warranty**

COMPLAINT: ONE OF THE KITCHEN CABINETS IS HANGING LOWER THAN THE OTHER

CAUSE: NOTED ON DAF

CORRECTION: CABINETS NEED TO BE ADJUSTED TO CORRECT POSITION

LABOR .20

**Labor**

Job #	Description	Hours	Total
2	ADJUSTED	0.20	33.00
<b>Subtotal for Job #2:</b>			<b>33.00</b>

**Job #3 - Warranty**

COMPLAINT: CEILING STRIP OVER THEATER SEATING IS DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE CEILING STRIP

LABOR .50

**Labor**

Job #	Description	Hours	Total
3	REPLACED CEILING STRIP	0.25	41.25

Customer #: 47602  
 TRIAM RV CENTER-EAST  
 TN,



**Parts**

Part #	Description	Qty	Price	Total
F100736011	CEILING TRIM	1.00	2.18	2.18

**Other Services**

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	5.00	5.00
NII	SPECIAL PACKAGE	1.00	13.00	13.00

**Subtotal for Job #3: 61.43**

**Job #4 - Warranty**

COMPLAINT: DRIVER SIDE FRONT TIRE HAD TO BE REPAIRED AT WALMART BY THE DELIVERY COMPLY. TIRE HAD A NAIL AND IT WAS PATCHED AT WALMART.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE THE DAMAGED TIRE AND REPLACE WITH NEW LABOR .50

**Labor**

Job #	Description	Hours	Total
4	INSTALLED TIRE	0.50	82.50

**Parts**

Part #	Description	Qty	Price	Total
F100201277	GOODYEAR ENDURANCE RADIAL TIRE	1.00	251.82	251.82

**Other Services**

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	132.84	132.84

**Subtotal for Job #4: 467.16**

Parts Total: 254.00  
 Labour Total: 206.25  
 Sublet Total: 0.00  
 Extras Total: 150.84

**WORK ORDER TOTAL: 611.09**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X \_\_\_\_\_

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 23 Oct 2025



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

