

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080
 TRI AM RV CENTER OF EAST TN
 1202 IDELL ROAD (I-81 EXIT 23)
 BULLS GAP, TN 37711
 USA

CLAIM STATUS Paid
 CLAIM 2427630
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TRLA29TD466795
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 010 / 010B
 ITEM # RLT2511S
 DEALER RO # 26037
 CLAIM START DATE 09/08/2025
 CLAIM END DATE 10/23/2025

Labor rate: \$165.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-100-02-00-001044 Drawer Guides or Tracks, pair - Interior/Cabinetry/Adjust/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-09-08 11:39:01 :: Complaint: The drawer in bedroom wall will not go into correct position. The guide only allows one side to go in all the way Cause: Noted on DAF Correction: Remove drawer and guide, relocate the drawer guide to allow the drawer to close correctly
Model# **Dlr Sub Hrs** 0.30 **Sub Labor Amt** \$49.50
Serial# **Appr Hrs** 0.30 **Appr Labor Amt** \$49.50
Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 30-100-24-00-001043 Drawer Front - Interior/Cabinetry/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-09-08 11:40:32 :: Complaint: One of the kitchen cabinets is hanging lower than the other Cause: Noted on DAF Correction: Cabinets need to be adjusted to correct position
Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$33.00
Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$33.00
Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 30-102-01-00-004033 Snap-In Trim, each - Interior/Panels, Ceilings, & Interior Moldings/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : ashlee@dealer-advisors.com, 2025-09-08 11:43:11 :: Complaint: Ceiling strip over theater seating is damaged Cause: Noted on DAF Correction: Replace ceiling strip
Model# **Dlr Sub Hrs** 0.50 **Sub Labor Amt** \$82.50
Serial# **Appr Hrs** 0.25 **Appr Labor Amt** \$41.25
Notes
 Hello, the labor time submitted to Forest River has been reviewed and reduced based on the photos and description provided as well as the most applicable flat rate code. Thank you

Part

Line# 1 **Item #** **Description**
 F100736011 TRIM - PFL: CIELING TRIM, ROUNDED - ESCAPE WHITE - 1.4" X 95 1/2" - V# 106589 | X
Model # **Serial #** **Part tag**
Sub Qty 1.00 **Sub Dlr Price** \$2.18 **Sub Freight** \$5.00
Appr Qty 1.00 **Appr Dlr Price** \$2.18 **Appr Freight** \$5.00

Notes

| | | | | | | |
|----------------|----------------|------|--|---------|-----------------|---------|
| Line# 2 | Item # | | Description | | | |
| | F100270074 | | SPECIAL PACKAGING - MOLDINGS 9' OR LESS (INCLUDING FASCIA, BATTEN, STILES & EXTERIOR MOLDINGS) | | | |
| | Model # | | Serial # | | Part tag | |
| | Sub Qty | 1.00 | Sub Dlr Price | \$13.00 | Sub Freight | \$0.00 |
| | Appr Qty | 1.00 | Appr Dlr Price | \$0.00 | Appr Freight | \$13.00 |

Notes

Hello, Forest River respectfully does not pay for markup on special packaging and or Freight cost. Special package cost/Freight cost Adjusted to \$13.00 made in processing. Thank you

Labor

| | | |
|----------------|-----------------------|--|
| Line# 4 | Operation Code | Operational Description |
| | 10-3-01-19-000075 | Tire only - No Rim, Wheel - Frame & Chassis/Wheels, Tires, Hubcaps/Replace/Tires |

Complaint, Cause, Correction

Original Note : ashlee@dealer-advisors.com, 2025-09-08 11:45:36 :: Complaint: Driver side front tire had to be repaired at Walmart by the delivery company. Tire had a nail and it was patched at Walmart Cause: Noted on DAF Correction: Remove the damaged tire and replace with new

| | | | | |
|----------------|--------------------|------|-----------------------|---------|
| Model# | Dlr Sub Hrs | 0.50 | Sub Labor Amt | \$82.50 |
| Serial# | Appr Hrs | 0.50 | Appr Labor Amt | \$82.50 |

Notes

Authorized for the dealer to replace tire only. Thank you!

Part

| | | | | | | |
|----------------|----------------|------|--|----------|-----------------|----------|
| Line# 1 | Item # | | Description | | | |
| | F100201277 | | TIRE - 11M-0: TIRE ONLY, ST205/75R14, LRD, GOODYEAR ENDURANCE RADIAL TIRE - 14 X 5.5 - V# GYEN-205RD-140 | | | |
| | Model # | | Serial # | | Part tag | |
| | Sub Qty | 1.00 | Sub Dlr Price | \$251.82 | Sub Freight | \$132.84 |
| | Appr Qty | 1.00 | Appr Dlr Price | \$251.82 | Appr Freight | \$132.84 |

Notes

| | | | | | |
|------------------|-----------------|----------|-----------------|-----------------|----------|
| Submitted | Labor Amt | \$247.50 | Approved | Labor Amt | \$206.25 |
| | Parts & Freight | \$408.74 | | Parts & Freight | \$404.84 |
| | Total | \$656.24 | | Total | \$611.09 |

DEALER _____ DATE _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE

All repairs described have been inspected and are satisfactory.