



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26037



WO #: 26037

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11203
Stock Desc: 2026 TT FOREST RIVER
ROCKWOOD MINI 2511S
Model: 2511S
Serial #: 4X4TRLA29TD466795
Chassis #:
Mileage: 0
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 08 SEP 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: THE DRAWER IN BEDROOM WALL WILL NOT GO IN CORRECT, THE GUIDE ONLY
ALLOWS ONE SIDE TO GO IN ALL THE WAY

CAUSE: NOTED ON DAF

CORRECTION: REMOVE DRAWER AND GUIDE, RELOACTE THE DRAWER GUIDE TO ALLOW THE
DRAWER TO CLOSE CORRECTLY.
LABOR .30

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: ONE OF THE KITCHEN CABINETS IS HANGING LOWER THAN THE OTHER

CAUSE: NOTED ON DAF

CORRECTION: CABINETS NEED TO BE ADJUSTED TO CORRECT POSITION
LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CEILING STRIP OVER THEATER SEATING IS DAMAGED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE CEILING STRIP
LABOR .50

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: DRIVER SIDE FRONT TIRE HAD TO BE REPAIRED AT WALMART BY THE DELIVERY
COMPLANY. TIRE HAD A NAIL AND IT WAS PATCHED AT WALMART.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE THE DAMAGED TIRE AND REPLACE WITH NEW

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



LABOR .50

Subtotal for Job #4: 0.00

W/O: 26037

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 08 Sep 2025



Customer Work Order

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

