



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26058



WO #: 26058

Customer: 47602 - TRIAM RV CENTER-EAST TN
 Address: 1202 IDELL ROAD
 BULLS GAP, TN
 37711

Home Phone: 423-235-1167

Work Phone:
 Author: S.DAVIS
 Location: IH
 Invoice #:

Stock #: 11209
 Stock Desc: 2026 FW DUTCHMEN ASTORIA
 260RK
 Model: 260RK
 Serial #: 4YDFAAM21TZ915168
 Chassis #:
 Mileage: 0
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 11 SEP 25
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed: 01 DEC 25
 Warr. Date:

Job #1 - Warranty

COMPLAINT: NDS REAR EXTERIOR TRIM DENTED

CAUSE: NOTED ON DAF
 DAMAGED AT INSTALL FROM FACTORY

CORRECTION: REMOVE VINYL INSERT, REMOVE DENTED TRIM, CLEAN AREA, REPLACE WITH
 NEW TRIM AND VINYL INSERT, ADD BUTYL AND SEALANT TO THE AREA
 LABOR 1.5

Labor

Job #	Description	Hours	Total
1	REPALCED AND REPAIRED	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
20-6982	021-85202-16 LONG LEG CORNER MOLDING 16'	1.00	60.00	60.00
JR10015	VINYL INSERT 25' BLACK	1.00	13.00	13.00
79233	BUTYL TAPE 1/8X3/4	1.00	10.11	10.11
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	11.86	11.86

Subtotal for Job #1: 182.47

Job #2 - Warranty

COMPLAINT: THE LINO FLOORING HAS SEVERAL BLACK SPOTS IN THE KITCHEN AND LIVING
 AREA.

CAUSE: NOTED ON DAF
 THIS IS NOT A SPOT THAT CAN BE CLEANED WITH WATER ONLY. THESE ARE PUDDY LIKE SPOTS.

CORRECTION: EACH SPOT WILL HAVE TO BE GENTLY AND SOFTLY REMOVED AND THEN CLEAN
 EACH AREA.
 LABOR 1.0

Labor

Job #	Description	Hours	Total
2	CLEANED	1.00	175.00

Customer #: 47602
 TRI-AM RV CENTER-EAST
 TN,



Subtotal for Job #2: 175.00

W/O: 26058

Job #3 - Warranty

COMPLAINT: INTERIOR ENTRY DOOR RING IS DENTED AND DAMAGED

CAUSE: NOTED ON DAF
DAMAGED AT INSTALL FROM FACTORY

CORRECTION: REMOVE DAMAGED TRIM AND REPLACE WITH NEW
LABOR 1.0

Labor

Job #	Description	Hours	Total
3	REPLACED DOOR RING	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
721744	METAL DOOR TRIM	1.00	10.02	10.02

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	46.77	46.77

Subtotal for Job #3: 91.79

Job #4 - Warranty

COMPLAINT: SMALL HOLE IN WALL NEXT TO BATHROOM

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
CLAIM DENIED

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: WHITE PAINT ON THE LINO FLOORING IN FRONT OF THE BATHROOM

CAUSE: NOTED ON DAF

CORRECTION: CLEAN PAINT OFF FLOOR
LABOR .20

Labor

Job #	Description	Hours	Total
5	CLEAN	0.20	35.00

Subtotal for Job #5: 35.00

Job #6 - Warranty

COMPLAINT: ENTRY DOOR STEPS ARE SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: PAINT AND BLEND THE AREA ON THE STEPS
LABOR .50

Labor

Job #	Description	Hours	Total
6	PAINT AND BLEND AREA	0.40	70.00

Parts

Part #	Description	Qty	Price	Total
4717	RUST-OLEUM SPRAY PAINT; SATIN BLACK	1.00	8.41	8.41



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #6: 78.41

Job #7 - Warranty

COMPLAINT: AWNING ARM WILL NOT GO ALL THE WAY IN AS DESIGNED

CAUSE: NOTED ON DAF

CORRECTION: ADJUST AWNING ARM TO OPERATE AS DESIGNED
DENIED CLAIM

Subtotal for Job #7: 0.00

Parts Total:	113.40
Labour Total:	402.50
Sublet Total:	0.00
Extras Total:	46.77
WORK ORDER TOTAL:	562.67

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 02 Dec 2025

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

W/O: 26058

