



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 26058



WO #: 26058

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:  
Author: S.DAVIS  
Location: IH  
Invoice #:

Stock #: 11209  
Stock Desc: 2026 FW DUTCHMEN ASTORIA  
260RK  
Model: 260RK  
Serial #: 4YDFAAM21TZ915168  
Chassis #:  
Mileage: 0  
Key #:  
Req'n #:  
License #:  
Trim:

Purchase Date:  
Date In: 11 SEP 25  
Promise Date:  
Promise Time:  
Schedule Date:  
Completed:  
Warr. Date:

**Job #1 - Warranty**

COMPLAINT: NDS REAR EXTERIOR TRIM DENTED

CAUSE: NOTED ON DAF  
DAMAGED AT INSTALL FROM FACTORY

CORRECTION: REMOVE VINYL INSERT, REMOVE DENTED TRIM, CLEAN AREA, REPLACE WITH  
NEW TRIM AND VINYL INSERT, ADD BUTYL AND SEALANT TO THE AREA  
LABOR 1.5

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: THE LINO FLOORING HAS SEVERAL BLACK SPOTS IN THE KITCHEN AND LIVING  
AREA.

CAUSE: NOTED ON DAF  
THIS IS NOT A SPOT THAT CAN BE CLEANED WITH WATER ONLY. THESE ARE PUDDY LIKE SPOTS.

CORRECTION: EACH SPOT WILL HAVE TO BE GENTLY AND SOFTLY REMOVED AND THEN CLEAN  
EACH AREA.  
LABOR 1.0

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: INTERIOR ENTRY DOOR RING IS DENTED AND DAMAGED

CAUSE: NOTED ON DAF  
DAMAGED AT INSTALL FROM FACTORY

CORRECTION: REMOVE DAMAGED TRIM AND REPLACE WITH NEW  
LABOR 1.0

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: SMALL HOLE IN WALL NEXT TO BATHROOM

CAUSE: NOTED ON DAF

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



CORRECTION: FILL, COLOR AND BLEND AREA  
LABOR .30

Subtotal for Job #4: 0.00

**Job #5 - Warranty**

COMPLAINT: WHITE PAINT ON THE LINO FLOORING IN FRONT OF THE BATHROOM

CAUSE: NOTED ON DAF

CORRECTION: CLEAN PAINT OFF FLOOR

LABOR .20

Subtotal for Job #5: 0.00

**Job #6 - Warranty**

COMPLAINT: ENTRY DOOR STEPS ARE SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: PAINT AND BLEND THE AREA ON THE STEPS

LABOR .50

Subtotal for Job #6: 0.00

**Job #7 - Warranty**

COMPLAINT: AWNING ARM WILL NOT GO ALL THE WAY IN AS DESIGNED

CAUSE: NOTED ON DAF

CORRECTION: ADJUST AWNING ARM TO OPERATE AS DESIGNED

LABOR .50

Subtotal for Job #7: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X \_\_\_\_\_  
-----

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 30 Sep 2025

Customer Signature : \_\_\_\_\_

W/O : 26058



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

