



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26059



WO #: 26059

Customer: 47602 - TRIAM RV CENTER-EAST TN
 Address: 1202 IDELL ROAD
 BULLS GAP, TN
 37711

Home Phone: 423-235-1167

Work Phone:
 Author: S.DAVIS
 Location: IH
 Invoice #:

Stock #: 11204
 Stock Desc: 2026 FW FOREST RIVER
 SANDPIPER 4002FB
 Model: 4002FB
 Serial #: 4X4FSAS24TJ048716
 Chassis #:
 Mileage:0
 Key #:
 Req'n #:
 License #:
 Trim:

Purchase Date:
 Date In: 11 SEP 25
 Promise Date:
 Promise Time:
 Schedule Date:
 Completed: 21 NOV 25
 Warr. Date:

Job #1 - Warranty

COMPLAINT: SEAM TAPE ON CORRECTLY AND IS WRINKLED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE SEAM TAPE
 LABOR .30

Labor

Job #	Description	Hours	Total
1	REPLACED SEAM TAPE	0.30	49.50

Parts

Part #	Description	Qty	Price	Total
F100435667	SEAM TAPE	1.00	19.41	19.41

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	18.81	18.81

Subtotal for Job #1: 87.72

Job #2 - Warranty

COMPLAINT: CUP HOLDER ON DOUBLE SEATING IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REPLACE CUP HOLDER
 LABOR .50

Labor

Job #	Description	Hours	Total
2	REPLACED CUP HOLDER	0.20	33.00

Parts

Part #	Description	Qty	Price	Total
2024116815	CUP HOLDER	1.00	8.37	8.37

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	12.66	12.66

Subtotal for Job #2: 54.03

Customer #: 47602
 TRIAM RV CENTER-EAST
 TN,



Job #3 - Warranty

COMPLAINT: STILE AT PANTRY IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20

Labor

Job #	Description	Hours	Total
3	FILL AND COLOR	0.20	33.00

Subtotal for Job #3: 33.00

Job #4 - Warranty

COMPLAINT: STICKY GLUE ON CORNER OF KITCHEN ISLAND

CAUSE: NOTED ON DAF

CORRECTION: REMOVE GLUE AND BUFF COUNTER
LABOR .50

Labor

Job #	Description	Hours	Total
4	CLEANED AND BUFFED COUNTER	0.50	82.50

Subtotal for Job #4: 82.50

Job #5 - Warranty

COMPLAINT: FRONT AWNING HAS A HOLE IN FABRIC

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE AWNING FABRIC
LABOR 1.5

Parts

Part #	Description	Qty	Price	Total
F100713520	AWNING FABRIC ONLY	1.00	316.54	316.54

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	0.00	0.00

Subtotal for Job #5: 316.54

Job #6 - Warranty

COMPLAINT: KITCHEN CABINET ABOVE BAR HAS GLUE ACROSS THE LOWER SECTION

CAUSE: NOTED ON DAF

CORRECTION: REPLACE CABINET DOOR, GLUE WILL NOT COME OFF
LABOR .30

Parts

Part #	Description	Qty	Price	Total
F100608708	CABINET DOOR	1.00	57.23	57.23

Subtotal for Job #6: 57.23

Job #7 - Warranty

COMPLAINT: BATHROOM DOOR STILE HAS A CHIP IN THE LOWER AREA

CAUSE: NOTED ON DAF



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #7: 0.00

W/O: 26059

Parts Total: 401.55
Labour Total: 198.00
Sublet Total: 0.00
Extras Total: 31.47
WORK ORDER TOTAL: 631.02

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 21 Nov 2025



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Work Order

