



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 26071



WO #: 26071

Customer: 59072 - EXTREME AUTOMOTIVE,  
KYKERS  
Address: 1201 TUSCULUM BLVD  
GREENEVILLE, TN  
37745  
Home Phone: 423-525-5147  
Work Phone:  
Author: CLP  
Location: IH  
Invoice #:

Stock #: 10911  
Stock Desc: 2024 FW FOREST RIVER CEDAR  
CREEK 391WOW  
Model: 391WOW  
Serial #: 4X4FCRR27RS233105  
Chassis #:  
Mileage:  
Key #: 13200  
Req'n #:  
License #:  
Trim:

Purchase Date: 28 DEC 24  
Date In: 15 SEP 25  
Promise Date:  
Promise Time:  
Schedule Date:  
Completed:  
Warr. Date: 28 DEC 24

#### Job #1 - Warranty

COMPLAINT: JWRAP ON DOOR SIDE DRIPS WHEN FRONT AC IS RUNNING

CAUSE: WATER LEAKING THROUGH RAIN GUTTER SEAM AND RUNNING DOWN THE SIDE OF  
UNIT

CORRECTION: RESEAL AREA  
LABOR .20

Subtotal for Job #1: 0.00

#### Job #2 - Warranty

COMPLAINT: SCREWS ARE BACKING OUT OF SIDE OF UNIT

CAUSE: SCREWS WORKED LOOSE AND CAME OUT

CORRECTION: RESECURE SCREWS AND REPLACE THE ONES MISSING  
LABOR .20

Subtotal for Job #2: 0.00

#### Job #3 - Warranty

FRONT AC IS HUMMING WHILE RUNNING

Subtotal for Job #3: 0.00

#### Job #4 - Warranty

COMPLAINT: TRIM IN FRONT BEDROOM IS FALLING OFF IN CLOSET AND ON SIDE OF SLIDE

CAUSE: TRIM NOT SECURED IN CORRECTLY AND IS COMING LOOSE

CORRECTION: RESECURE TRIM IN PLACE  
LABOR .20

Subtotal for Job #4: 0.00

#### Job #5 - Warranty

BEAM ACROSS CEILING IS FALLING DOWN

Customer #: 59072  
EXTREME AUTOMOTIVE,  
KYKERS



**Subtotal for Job #5: 0.00****Job #6 - Warranty**

COMPLAINT: SHOWER HANDLE FELL APART DRIVING DOWN THE ROAD, CUST FOUND IT BROKE OFF WHEN THEY ARRIVED AT THE CAMP GROUND

CAUSE: FAULTY SHOWER HANDLE

CORRECTION: REPLACE SHOWER HANDLE  
AND WATER TEST  
LABOR .30

**Subtotal for Job #6: 0.00****Job #7 - Warranty**

COMPLAINT: LATCH ON TV FALSE WALL WILL NOT STAY CLOSED AND FALSE PANEL IS OPENING WHILE DRIVING DOWN THE ROAD CAUSING DAMAGE TO TRIM AND STILE

CAUSE: THE CATCH ON THE FALSE WALL IS BENT AND NOT LATCHING AS IT SHOULD. THIS IS ALLOWING THE DOOR TO COME OPEN IN TRANSIT AND DAMAGED THE DOOR.

CORRECTION: REMOVE ALL DAMAGED PARTS (LATCH AND STILE) REPLACE DAMAGED STILE AND LATCH ON FALSE WALL  
LABOR 2.0

**Subtotal for Job #7: 0.00****Job #8 - Warranty**

FRONT BASEMENT ON BOTH SIDES IS LEAKING

**Subtotal for Job #8: 0.00****Job #9 - Warranty**

COMPLAINT: CS PINBOX COVER IS BOWED

CAUSE: BOX INSTALLED INCORRECTLY AT FACTORY AND THIS HAS ALLOWED THE BOX TO BOW OVER TIME

CORRECTION: REMOVE DAMAGED PIN BOX AND REPLACE WITH NEW ONE  
LABOR 1.0

**Subtotal for Job #9: 0.00****Job #10 - Warranty**

SLIDE ON DOORSIDE WHEN CLOSED IS NOT SEALING ALL OF THE WAY

**Subtotal for Job #10: 0.00****Job #11 - Warranty**

COMPLAINT: DOORSIDE REAR DECALS ARE PEELING

CAUSE: DECALS ARE BUBBLING UP AT THE REAR CORNER

CORRECTION: REPLACE BOTH THE BLACK AND BLUE DECAL ON DS REAR  
LABOR 2.0

**Subtotal for Job #11: 0.00****Job #12 - External**

ACS WILL NOT COOL DOWN BELOW 78\* AT BEACH CUS WANTS TO KNOW IF DUCTS ARE CONNECTED THROUGH THE UNIT



Customer #: 59072  
EXTREME AUTOMOTIVE,  
KYKERS



Subtotal for Job #12: 0.00

W/O: 26071

Job #13 - Warranty

COMPLAINT: WOOD ON KITCHEN ISLAND IS SWELLED, CUS STATES THERE ARE NO LEAKS

CAUSE: CONNECTION TO KITCHEN SINK WAS DRIPPING OVER NIGHT AND SETTLED NEAR ISLAND. THIS CAUSED THE WOOD TO SWELL ON ISLAND.

CORRECTION: REMOVE ALL SWOLLEN WOOD. TIGHTEN THE FITTING AND REPLACE THE STILE AND ANY DAMAGED WOOD ON ISLAND  
LABOR 3.0

Other Services

| Code | Description            | Qty  | Price | Total |
|------|------------------------|------|-------|-------|
| SSE  | SHOP SUPPLIES EXTERNAL | 1.00 | N/C   | N/C   |

Subtotal for Job #13: 0.00

Job #14 - Warranty

COMPLAINT: STOVE HAS SURFACE SCRATCHES

CAUSE: STOVE IS GOUGDED ON THE SURFACE FROM THE GROMMETS NOT BEING THERE

CORRECTION: REPLACE STOVE  
LABOR 1.0

Subtotal for Job #14: 0.00

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**

Customer #: 59072  
EXTREME AUTOMOTIVE,  
KYKERS

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 21 Oct 2025

Customer Signature : \_\_\_\_\_