

APPOINTMENT DATE	9/22/2025	VEHICLE ARRIVED	9/22/2025	WSO DATE PREPARATION		CLAIM STATUS	Approval Pending	WARRANTY CLAIM No	KZ620057		
REPAIR COMPLETION DATE	12/19/2025	CUSTOMER NOTIFIED		VEHICLE PICKED UP		CREDIT DATE		CREDIT NUMBER			
RV SERIAL NUMBER	4EZTL3123S4046065	MAKE		CONNECT		MODEL	C301BHKSE	YEAR	2025		
PURCHASE DATE		6/30/2025									
DEALER				CUSTOMER				FACTORY USE ONLY			
NUMBER	TR1030	LABOR RATE	\$175.00	FEE RATE	15.00	CONTACT	MICHAEL ALLHOUSE				
NAME	Tri-Am RV Center of E. Tn, Inc			PHONE		ADDRESS	709 DOUGLAS DR		PHONE	559-907-5711	
ADDRESS	1202 Idell Road					CITY	JOHNSON CITY	STATE	TN	ZIP	37604
CITY	Bulls Gap	STATE	TN	ZIP	37711	EQUIP. SER. #		EQUIP. MODEL		EQUIP. MFR.	

WARRANTY CLAIM #	KZ620057	JOB OPERATION 1	Water pump is intermittently not pumping nwater	OPERATION CODE	3356	AUTHORIZATION #	JS5101613						
CAUSE	Due to manufacturer defect, pump diaphragm will not pressurize and is intermittently working			HOURS	0.50	AMOUNT	\$87.50						
<p style="text-align: center; font-size: 2em;">18x10x2 3LSS</p>				SUPPLIER NAME	RANGER DISTRIBUTION		STATUS	OpenPR					
				LABOR	\$87.50	PARTS		MARK UP		FREIGHT		SUBLET	
				PART #		CHARGEBACK #			Dup	N			
				JOB OPERATION DENIAL CODE		INITIALS							
				REMEDY	Remove and reinstall false wall, replace water pump and test								

PART NUMBER	PART DESCRIPTION	RETURN TAG #	QUANTITY	UNIT	TOTAL PARTS	ADJUSTED TOTAL
160901	PUMP,WATER,WITH FILTER,12V,3.0 GPM		0	\$51.70	\$0.00	\$0.00
160901	PUMP,WATER,WITH FILTER,12V,3.0 GPM		1	\$45.73	\$45.73	\$52.59
SUB-TOTAL:		LABOR	\$87.50	PARTS	\$45.73	

WARRANTY CLAIM #	KZ620057	JOB OPERATION 2	Customer states there is a leak when flushing black tank	OPERATION CODE	3383	AUTHORIZATION #	JS5101614						
CAUSE	Due to defect vacuum breaker, under bathroom sink is leaking			HOURS	0.40	AMOUNT	\$70.00						
				SUPPLIER NAME	B&B MOLDING		STATUS	OpenPR					
				LABOR	\$70.00	PARTS		MARK UP		FREIGHT		SUBLET	
				PART #		CHARGEBACK #			Dup	N			
				JOB OPERATION DENIAL CODE		INITIALS							
				REMEDY	Replace vacuum breaker								

PART NUMBER	PART DESCRIPTION	RETURN TAG #	QUANTITY	UNIT	TOTAL PARTS	ADJUSTED TOTAL
121585	ASSEMBLY,FLUSHER KIT,BLACK,PLASTIC,F/HOLDING TANK,INCLUDES WATER INLET, 571 VALVE, & 571 SPRAYER(GLU		0	\$23.30	\$0.00	\$0.00
121585	ASSEMBLY,FLUSHER KIT,BLACK,PLASTIC,F/HOLDING TANK,INCLUDES WATER INLET, 571 VALVE, & 571 SPRAYER(GLU		1	\$20.61	\$20.61	\$23.70
SUB-TOTAL:		LABOR	\$70.00	PARTS	\$20.61	

TRI - AM RV CENTER
(260) 768-4016
1202 IDELL ROAD
BULLS GAP TN 37711


3 LBS

DWT: 18,10,2

SHIP TO:

KZ - RV INC -
(260) 768-4016
9270 W US 20

SHIPSHEWANA IN 46565



IN 465 9 - 03



UPS GROUND

TRACKING #: 1Z 660 241 03 7095 3034



BILLING: P/P

REF 1:KZ620067



SEE NOTICE ON REVERSE regarding UPS terms, and notice of limitation of liability. Where Marked by a "PS" symbol, this label authorizes UPS to act as the shipping agent for export control and customs purposes. If exported from the US, shipper certifies that the commodities, technology or software were exported from the US in accordance with the Export Administration Regulations. Diversion contrary to law is prohibited.

For information about UPS's privacy practices or to opt out from the sale of personal information, please see the UPS Privacy Notice at www.ups.com
R8D RFP 0925