



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

Estimate: 26095 ALLSHOUSE,  
MICHAEL



Estimate: 26095 (Appointment Date: 24 SEP 2025 - Time: 09:00am)

Customer: 92984 - ALLSHOUSE, MICHAEL  
Address: 709 DOUGLAS DR  
JOHNSON CITY, TN  
37604

Home Phone: (559) 907-5711

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 11116

Stock Desc: 2025 TT KZ-RV CONNECT SE

301BHKSE

Model: 301BHKSE

Serial #: 4EZTL3123S4046065

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 30 JUN 25

Date In: 22 SEP 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 30 JUN 25

**Job #2 - Warranty**

COMPLAINT: WATER PUMP IS INTERMITTENTLY NOT PUMPING WATER

CAUSE: DUE TO MANUFACTURER DEFECT PUMP DIAPHRAM WILL NOT PRESSURIZE AND IS INTERMITTENTLY WORKING

CORRECTION: REMOVE AND REINSTALL FALSE WALL, REPLACE WATER PUMP AND TEST SYSTEM  
LABOR 1.0

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: CUSTOMER STATES THERE IS A LEAK WHEN FLUSHING BLACK TANK

CAUSE: DUE TO DEFECT VACUUM BREAKER UNDER BATHROOM SINK IS LEAKING

CORRECTION: REPLACE VACUUM BREAKER  
LABOR .5

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: CUSTOMER STATES THAT EVEN WITH REGULATOR THE KITCHEN FAUCET HAS A SLOW DRIP

CAUSE: DUE TO DEFECT KITCHEN FAUCET IS ALLOWING WATER THROUGH EVEN WHEN SHUT OFF

CORRECTION: REPLACE KITCHEN FAUCET AND TEST  
LABOR .5



**Subtotal for Job #4: 0.00**

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00  
Tax Total: 0.00  
Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 16 Oct 2025

Customer Estimate

