



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26116



WO #: 26116

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11216
Stock Desc: 2026 FW FOREST RIVER CEDAR
CREEK 39RKB
Model: 39RKB
Serial #: 4X4FCRR26TS235368
Chassis #:
Mileage: 0
Key #:
Req'n #:
License #:
Trim: 39RKB

Purchase Date:
Date In: 24 SEP 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: SCRATCH ON KITCHEN CABINET DOOR

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: KITCHEN STILE BEHIND SEATING NAIL HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THE WINDOW IN THE SITTING ROOM IS SHOWING DAYLIGHT AT THE BOTTOM

CAUSE: NOTED ON DAF
OUTTER TRIM WAS NOT INSTALLED CORRECTLY ALLOWING LIGHT TO COME THROUGH THE
BOTTOM

CORRECTION: REMOVE SET SCREWS ON INTERIOR TRIM RING AROUND THE WINDOW AND
RESECURE BACK IN CORRECT PLACE.
LABOR .50

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CHIPS IN BEDROOM DOOR IN DIFF AREAS

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: STILE ON LIVING ROOM SLIDE HAS DEEP SCRATCHES IN SEVERAL PLACES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND THE AREA
LABOR .20

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: FRIDGE IS NOT SECURED IN PLACE ON THE BOTTOM. FRIDGE IS STICKING OUT AT THE BOTTOM ALOT MORE THAN THE TOP.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE FRIDGE AND RESECURE BACK IN CORRECT PLACE
LABOR .50

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: THE MANTEL WHERE THE TV AND FIREPLACE IS HAS SCRATCHES ALL ACROSS THE TOP. THE CORNER TRIM IS CRACKED AND THE FLOATING SHELF IS CRACKED AND DAMGED AS WELL.

CAUSE: NOTED ON DAF

CORRECTION: REMOVE TV AND FIREPLACE. REMOVE THE DAMAGED MANTEL AND TRIM. REPLACE THE MANTEL AND TRIM WITH NEW. REINSTALL TV AND FIREPLACE.
LABOR 3.1

Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: WINDOW IN THE BEDROOM ON DOOR SIDE HAS A GAP AT THE BOTTOM, WINDOW NOT CLOSING CORRECTLY

CAUSE: NOTED ON DAF
OUTTER TRIM NOT INSTALLED CORRECTLY ALLOWING LIGHT OT COME IN AT THE BOTTOM

CORRECTION: REMOVE SET SCREWS IN THE TRIM RING ON THE INTERIOR AND THEN RESECURE BACK IN CORRECT PLACE.
LABOR .50

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: WIRES ARE STRIPPED ON THE ODS SLIDE OVER THE TIRE

CAUSE: NOTED ON DAF
WIRES ARE LAYING ON THE TIRES AND RUBBING CAUSING THE WIRES TO BE DAMAGED

CORRECTION: REMOVE AND REINSTALL FLEX GUARD, REPLACE WIRE LOOM, REPLACE ALL DAMAGED WIRE AND INSTALL WITH WATER PROOF CONNECTIONS.
LABOR 2.0



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #9: 0.00

W/O: 26116

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 25 Sep 2025



Customer Work Order

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

