

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080  
 TRI AM RV CENTER OF EAST TN  
 1202 IDELL ROAD (I-81 EXIT 23)  
 BULLS GAP, TN 37711  
 USA

CLAIM STATUS Paid  
 CLAIM 2447995  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4TRLB24TD466959  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 010 / 010B  
 ITEM # RLT2506FK  
 DEALER RO # 26122  
 CLAIM START DATE 09/25/2025  
 CLAIM END DATE 10/27/2025

Labor rate: \$165.00  
 OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

Line# 1      **Operation Code**      **Operational Description**  
 20-66-01-00-002294      Screen Door - Exterior/Entry Doors/Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : ashlee@dealer-advisors.com, 2025-09-25 11:38:41 :: Complaint: Paint on interior entry door trim ring Cause: Noted on DAF Correction: Paint and blend area  
**Model#**      **Dlr Sub Hrs**      0.20      **Sub Labor Amt** \$33.00  
**Serial#**      **Appr Hrs**      0.20      **Appr Labor Amt** \$33.00  
**Notes**  
 We have updated the repair code to a more appropriate one based on the identified root cause of this repair request

### Labor

Line# 2      **Operation Code**      **Operational Description**  
 30-102-24-00-001101      Slide Out Fascia, each section - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : ashlee@dealer-advisors.com, 2025-09-25 11:40:47 :: Complaint: Stile over living area slide has several holes on the right side Cause: Noted on DAF, damaged at install Correction: Fill, color, and blend area  
**Model#**      **Dlr Sub Hrs**      0.20      **Sub Labor Amt** \$33.00  
**Serial#**      **Appr Hrs**      0.20      **Appr Labor Amt** \$33.00  
**Notes**  
 changing to a better suited repair code.

### Labor

Line# 3      **Operation Code**      **Operational Description**  
 30-100-24-00-001046      Cabinet Door - Interior/Cabinetry/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : ashlee@dealer-advisors.com, 2025-09-25 11:41:58 :: Complaint: Chunk is missing on the kitchen side pantry door Cause: Noted on DAF Correction: Fill, color, and blend area  
**Model#**      **Dlr Sub Hrs**      0.30      **Sub Labor Amt** \$49.50  
**Serial#**      **Appr Hrs**      0.30      **Appr Labor Amt** \$49.50  
**Notes**

**Submitted**      Labor Amt      \$115.50  
 Parts & Freight      \$0.00  
 Total      \$115.50

**Approved**      Labor Amt      \$115.50  
 Parts & Freight      \$0.00  
 Total      \$115.50

---

**DEALER** **DATE**  
**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

---

**CUSTOMER** **DATE**  
**SIGNATURE**

All repairs described have been inspected and are satisfactory.