



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26132



WO #: 26132

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11213
Stock Desc: 2026 TT KZ-RV CONNECT 313MK
Model: 313MK
Serial #: 4EZTL3322T4088810
Chassis #:
Mileage:0
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 26 SEP 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: VALANCE AT REAR WINDOW NDS IS PEELING

CAUSE: NOTED ON DAF

CORRECTION: TRIM THE PAPER, COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: REAR WINDOW ON UNIT IS LEAKING AND ALLOWING WATER TO GET ON THE BACK OF THE SEATING.

CAUSE: NOTED ON DAF
MANUFACTOR DEFECT IN WINDOW

CORRECTION: REMOVE FAULTY WINDOW, CLEAN AREA, REPLACE WITH NEW WINDOW, RESEAL AREA AND WATER TEST
LABOR 1.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: STILE AT FIREPLACE IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: KITCHEN DRAWER BESIDE STOVE RUBS AGAINST THE STILE WHEN OPENING AND CLOSING

CAUSE: NOTED ON DAF
DOOR IS OUT OF ADJUSTMENT

CORRECTION: REMOVE DRAWER AND GUIDES, COLOR AND BLEND ANY DAMAGE TO THE CABINET, REINSTALL GUIDES TO OPERATE CORRECTLY

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



LABOR .50

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: KITCHEN STILE IS CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: SHADE TO THE LEFT OF THE SEATING WILL NOT GO UP

CAUSE: NOTED ON DAF

CORRECTION: REMOVE VALANCE AND SHADE, ADJUST SHADE, REINSTALL SHADE AND VALANCE
LABOR .50

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: SECURITY STRAP FOR BEDROOM CLOSET DOOR WAS NEVER INSTALL

CAUSE: NOTED ON DAF
NEVER INSTALLED AT FACTORY, NO HOLES TO PROVE INSTALL

CORRECTION: INSTALL SECURITY STRAP IN CORRECT PLACE
LABOR .20

Subtotal for Job #7: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 26 Sep 2025

Customer Signature : _____

W/O: 26132



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

