



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26142



WO #: 26142

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11223

Stock Desc: 2026 FW FOREST RIVER CEDAR

CREEK 29RL

Model: 29RL

Serial #: 4X4FCRE23TS235365

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 01 OCT 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 29 NOV 25

Warr. Date:

Job #1 - Warranty

COMPLAINT: ENTRY DOOR STEPS ARE SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: CLEAN, PAINT AND BLEND AREA

LABOR .50

Labor

Job #	Description	Hours	Total
1	CLEAN AND PAINT	0.50	82.50

Parts

Part #	Description	Qty	Price	Total
F100577087	STEP BOARD 11X28	1.00	49.93	49.93

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	31.28	31.28

Subtotal for Job #1: 163.71

Job #2 - Warranty

COMPLAINT: CABINET WINDOW ABOVE THE DOUBLE SEATING
IS SCRATCHED ON THE FRONT

CAUSE: NOTED ON DAF

CORRECTION: REMOVE SCRATCHED PLASTIC WINDOW, CLEAN AREA, REPLACE WINDOW WITH
NEW ONE, RESEAL AREA

LABOR 1.0

Labor

Job #	Description	Hours	Total
2	REPLACED WINDOW	1.00	165.00

Parts

Part #	Description	Qty	Price	Total
F100595284	GLASS INSERT	1.00	24.95	24.95

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	5.00	5.00

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #2: 194.95

Job #3 - Warranty

COMPLAINT: THE STILE INSERT ON THE LEFT SIDE OF THE KITCHEN SLIDE IS BOWING OUT.

CAUSE: NOTED ON DAF

INSERT IS TO LONG AND THIS IS ALLOWING THE INSERT TO BOW OUTWARD IN THE MIDDLE

CORRECTION: REMOVE THE INSERT, CUT TO FIT CORRECTLY THEN REINSTALL

LABOR .50

Labor

Job #	Description	Hours	Total
3	REPAIR	0.50	82.50

Subtotal for Job #3: 82.50

Job #4 - Warranty

COMPLAINT: SCRATCH/CHIP ON LEFT SIDE OF LIVING ROOM SLIDE

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR, BLEND AND CLEAN AREA

LABOR .20

Labor

Job #	Description	Hours	Total
4	FILL AND COLOR	0.20	33.00

Subtotal for Job #4: 33.00

Job #5 - Warranty

COMPLAINT: THREE CHIPS ON THE STILE TO HIDDEN CABINET

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .50

Labor

Job #	Description	Hours	Total
5	FILL AND COLOR	0.50	82.50

Subtotal for Job #5: 82.50

Job #6 - Warranty

COMPLAINT: CHIP ON KITCHEN CABINET BELOW SINK

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

Labor

Job #	Description	Hours	Total
6	FILL AND COLOR	0.20	33.00

Subtotal for Job #6: 33.00

Job #7 - Warranty

COMPLAINT: STILE INSERT ON THE RIGHT SIDE OF KITCHEN SLIDE IS BOWING OUT

CAUSE: NOTED ON DAF

STILE INSERT IN TO LONG AND ALLOWING IT TO BOW OUTWARD

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

CORRECTION: REMOVE INSERT,CUT TO CORRECTLY FIT THEN REINSTALL THE INSERT
LABOR .50

Labor			
Job #	Description	Hours	Total
7	REPAIR	0.50	82.50
Subtotal for Job #7:			82.50

Job #8 - Warranty

COMPLAINT: STEPS UP TO THE BEDROOM ARE SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE THE STEP BOARD
LABOR .50

Labor			
Job #	Description	Hours	Total
8	REPLACED BOARD	0.50	82.50
Subtotal for Job #8:			82.50

Parts Total: 74.88
Labour Total: 643.50
Sublet Total: 0.00
Extras Total: 36.28
WORK ORDER TOTAL: 754.66

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 29 Nov 2025

W/O: 26142



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

