



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26142



WO #: 26142

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11223

Stock Desc: 2026 FW FOREST RIVER CEDAR
CREEK 29RL

Model: 29RL

Serial #: 4X4FCRE23TS235365

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 01 OCT 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: ENTRY DOOR STEPS ARE SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: CLEAN, PAINT AND BLEND AREA
LABOR .50

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CABINET WINDOW ABOVE THE DOUBLE SEATING
IS SCRATCHED ON THE FRONT

CAUSE: NOTED ON DAF

CORRECTION: REMOVE SCRATCHED PLASTIC WINDOW, CLEAN AREA, REPLACE WINDOW WITH
NEW ONE, RESEAL AREA
LABOR 1.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THE STILE INSERT ON THE LEFT SIDE OF THE KITCHEN SLIDE IS BOWING OUT.

CAUSE: NOTED ON DAF

INSERT IS TOO LONG AND THIS IS ALLOWING THE INSERT TO BOW OUTWARD IN THE MIDDLE

CORRECTION: REMOVE THE INSERT, CUT TO FIT CORRECTLY THEN REINSTALL
LABOR .50

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: SCRATCH/CHIP ON LEFT SIDE OF LIVING ROOM SLIDE

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR, BLEND AND CLEAN AREA
LABOR .20

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00**Job #5 - Warranty**

COMPLAINT: THREE CHIPS ON THE STILE TO HIDDEN CABINET

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .50**Subtotal for Job #5: 0.00****Job #6 - Warranty**

COMPLAINT: CHIP ON KITCHEN CABINET BELOW SINK

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20**Subtotal for Job #6: 0.00****Job #7 - Warranty**

COMPLAINT: STILE INSERT ON THE RIGHT SIDE OF KITCHEN SLIDE IS BOWING OUT

CAUSE: NOTED ON DAF
STILE INSERT IN TO LONG AND ALLOWING IT TO BOW OUTWARDCORRECTION: REMOVE INSERT,CUT TO CORRECTLY FIT THEN REINSTALL THE INSERT
LABOR .50**Subtotal for Job #7: 0.00****Job #8 - Warranty**

COMPLAINT: STEPS UP TO THE BEDROOM ARE SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE AND REPLACE THE STEP BOARD
LABOR .50**Subtotal for Job #8: 0.00**Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00**WORK ORDER TOTAL: 0.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 01 Oct 2025

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,