



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 26144



WO #: 26144

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11220

Stock Desc: 2026 FW FOREST RIVER CEDAR

CREEK 29RL

Model: 29RL

Serial #: 4X4FCRE21TS235364

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 01 OCT 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 28 JAN 26

Warr. Date:

### Job #1 - Warranty

COMPLAINT: CHIPS/SCRATCHES ON STILE AT LIVING ROOM TV

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .30

#### Labor

| Job #                | Description | Hours | Total |
|----------------------|-------------|-------|-------|
| 1                    | FILL COLOR  | 0.30  | 49.50 |
| Subtotal for Job #1: |             |       | 49.50 |

### Job #2 - Warranty

COMPLAINT: EXIT WINDOW HAS DAYLIGHT COMING THROUGH AT THE BOTTOM

CAUSE: NOTED ON DAF

OUTTER TRIM WAS NOT INSTALLED CORRECTLY

CORRECTION: REMOVE SET SCREWS ON INTERIOR TRIM RING AROUND THE WINDOW. THEN  
RESECURE RING BACK IN CORRECT PLACE.

LABOR .50

#### Labor

| Job #                | Description     | Hours | Total |
|----------------------|-----------------|-------|-------|
| 2                    | REPAIRED WINDOW | 0.50  | 82.50 |
| Subtotal for Job #2: |                 |       | 82.50 |

### Job #3 - Warranty

COMPLAINT: SCRATCH ON KITCHEN TABLE

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .40

#### Labor

| Job # | Description    | Hours | Total |
|-------|----------------|-------|-------|
| 3     | FILL AND COLOR | 0.40  | 66.00 |

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



Subtotal for Job #3: 66.00

**Job #4 - Warranty**

COMPLAINT: FRIDGE DOOR SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE SCRATCHED DOOR AND REPLACE WITH NEW ONE  
LABOR .50

**Labor**

| Job # | Description             | Hours | Total |
|-------|-------------------------|-------|-------|
| 4     | REPLACED DOOR ON FRIDGE | 0.50  | 82.50 |

**Parts**

| Part #     | Description                                                                                          | Qty  | Price  | Total  |
|------------|------------------------------------------------------------------------------------------------------|------|--------|--------|
| F100303808 | REFRIGERATOR, SAMSUNG<br>RF18A5101SR, FRENCH DOOR, NO<br>HANDLES, STAINLESS STEEL  2021<br>M0001691- | 1.00 | 527.67 | 527.67 |

**Other Services**

| Code | Description          | Qty  | Price | Total |
|------|----------------------|------|-------|-------|
| SHP  | SHIPPING/FREIGHT FEE | 1.00 | 54.26 | 54.26 |

Subtotal for Job #4: 664.43

**Job #5 - Warranty**

COMPLAINT: RED SCRAPES ON THE DOOR SIDE FRONT CAP OF THE UNIT AT ARRIVAL

CAUSE: THIS WAS NOTED ON THE DEALER ACCEPTANCE FORM

CORRECTION: FIBERGLASS WORK, BUFFING,  
LABOR 4.0

**Labor**

| Job # | Description | Hours | Total  |
|-------|-------------|-------|--------|
| 5     | BUFFING     | 4.00  | 700.00 |

Subtotal for Job #5: 700.00

|                          |                 |
|--------------------------|-----------------|
| Parts Total:             | 527.67          |
| Labour Total:            | 980.50          |
| Sublet Total:            | 0.00            |
| Extras Total:            | 54.26           |
| <b>WORK ORDER TOTAL:</b> | <b>1,562.43</b> |

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 28 Jan 2026

W/O: 26144



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

