



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26272



WO #: 26272 (Appointment Date: 29 OCT 2025 - Time: 11:00am)

Customer: 82920 - MCMACKIN, TERRY
Address: 116 DUCKTOWN RD
LIMESTONE, TN
37681

Home Phone: 423-426-3230

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 11044

Stock Desc: (11044) 2025 FOREST RIVER

SANDPIPER 4003MB

Model: 4003MB

Serial #: 4X4FSAS2XSJ047682

Chassis #:

Mileage:

Key #: 8500

Req'n #:

License #:

Trim:

Purchase Date: 12 MAY 25

Date In: 27 OCT 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 12 MAY 25

Job #1 - Warranty

COMPLAINT: black tank flush inop

CAUSE: connected to tank flush found no water flow. removed hose and behind inlet and found water is flowing through inlet but not to the tank.

CORRECTION: need to test vacuum breaker. requesting time to gain access to breaker for determination of customers issue

labor to gain access .50

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: shock on pantry broke

CAUSE: shock on pantry is faulty and broke

CORRECTION: replace shock on pantry door
labor .50

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: switch in bunk house bedroom is inop

CAUSE: main light will not turn on by switch. tech inspected back of switch and found a wire has fallen and not connected to allow switch to work

CORRECTION: remove light switch, connect wire on back of light switch and reinstall light switch
labor .50

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: fridge has a gap and caused trim to be damaged on right side

CAUSE: fridge is mounted to far to the right side causing damage to slide fascia

CORRECTION: need to reposition fridge and replace the slide fascia to correct the issues
labor 1.5

Customer #: 82920
MCMACKIN, TERRY



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: trim coming loose in hall

CAUSE: trim came loose and no attached correctly

CORRECTION: resecure trim in place
labor .20

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: toilet seal is not holding water

CAUSE: ball seal is faulty and not allowing water to hold in toilet as it should

CORRECTION: replace ball seal and test
labor .50

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: auto level touch pad does not respond at times

CAUSE: panel does not react to normal touch, takes several times of pushing button firmly, then the button will stick

CORRECTION: auto level panel is faulty and not allowing the customer to use panel to level system
replace level panel
labor 1.0

Subtotal for Job #7: 0.00

Job #8 - External

WE INSTALLED A WASHER AND DRYER AND THE CUST STATED THERE IS DAMAGE TO THE DRYER VENT ON THE INSIDE. LOOK BEHIND THE DYER AND YOU CAN SEE THE ISSUE

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #8: 0.00

Job #9 - External

UNIT IS WINTERIZED BY CUST

Subtotal for Job #9: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 82920
MCMACKIN, TERRY

Customer Signature : _____

Date: 26 Nov 2025

W/O: 26272



Customer #: 82920
MCMACKIN, TERRY



Customer Work
Order

