



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26316



WO #: 26316

Customer: 90380 - BATES, CHARLES
Address: 171 ISLEY RD
BLOUNTVILLE, TN
37617
Home Phone: (423) 794-0085
Work Phone:
Author: SPD
Location: IH
Invoice #:

Stock #: 11139
Stock Desc: 2026 THFW FOREST RIVER ROGUE
351G2
Model: 351G2
Serial #: 4X4FVGL2XT5403602
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 03 OCT 25
Date In: 03 NOV 25
Promise Date:
Promise Time:
Schedule Date:
Completed: 17 DEC 25
Warr. Date: 03 OCT 25

Job #1 - Warranty

COMPLAINT: HANDRAIL IS STRIPPED OUT

CAUSE: ALUM BRACE STRIPPED OUT AND ALLOWED HAND RAIL TO COME OFF UNIT

CORRECTION: FILL HOLES, MOVE HANDLE UP ON UNIT WHEN INSTALLING, SEAL ANY AREA
NEEDED
LABOR 2.0

Labor

Job #	Description	Hours	Total
1	REPAIRED	2.00	330.00

Parts

Part #	Description	Qty	Price	Total
38-1870	PROFLEX SEALANT CLR 10OZ	1.00	11.86	11.86

Subtotal for Job #1: 341.86

Job #2 - Warranty

COMPLAINT: MIRROR IN KITCHEN IS CRACKED

CAUSE: MIRROR CRACKED WHILE TRAVELING

CORRECTION: REPLACE MIRROR AND FRAME
LABOR 1.5

Labor

Job #	Description	Hours	Total
2	REPLACED MIRROR	0.50	82.50

Parts

Part #	Description	Qty	Price	Total
F100655796	GLASS, BLACK MIRROR CBS CC CARBON FIBER PRINT 597, BLACK FRAME W/4 HOLES / 2025 U17, AREA 4, BACKWALL	1.00	109.12	109.12

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	194.01	194.01

Subtotal for Job #2: 385.63

Customer #: 90380
BATES, CHARLES



Job #3 - Warranty

COMPLAINT: RUG IN TOY HAULER PART HAS A BOW IN IT

CAUSE: WHEN RUG WAS INSTALLED IT WAS NOT CUT TO FIT CORRECTLY AND IS BOWING UP ALONG THE WALL

CORRECTION: REMOVE BLACK DIAMOND PLATE ON WALL, REMOVE BOTH DOORS TO ACCESS FLOORING. CUT THE FLOORING TO FIT CORRECTLY AND REINSTALL DIAMOND PLATE AND DOORS
LABOR 3.0**Labor**

Job #	Description	Hours	Total
3	REPAIRED AREA	3.00	495.00

Parts

Part #	Description	Qty	Price	Total
38-1865	PROFLEX RV SEALANT BLK	1.00	12.38	12.38

Subtotal for Job #3: 507.38**Job #4 - Warranty**

COMPLAINT: SCUFF ON PANEL IN GARAGE PART

CAUSE: STICKER WAS REMOVED FROM FACTORY AND CUSTOMER STATED THE TOP OF THE PANEL PEELED

CORRECTION: REPLACE PANEL
LABOR 2.0**Labor**

Job #	Description	Hours	Total
4	TOUCHED UP PANEL	0.50	82.50

Subtotal for Job #4: 82.50**Job #5 - Warranty**

COMPLAINT: MASTER BEDROOM SINK IS LEAKING UNDERNEATH/ TOTE WAS FULL OF WATER

CAUSE: TECH FOUND VACUUM BREAKER IS FAULTY AND LEAKING UNDER SINK

CORRECTION: REPLACE VACUUM BREAKER AND TEST
LABOR .50**Labor**

Job #	Description	Hours	Total
5	REPLACED VAC BREAKER	0.30	49.50

Parts

Part #	Description	Qty	Price	Total
F100110287	VACUUM BREAKER	1.00	12.42	12.42

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	5.00	5.00

Subtotal for Job #5: 66.92**Job #6 - Warranty**

COMPLAINT: CHECK THAT MONITOR PANEL IS WORKING

CORRECTION: PANEL WORKS AS DESIGNED AT THIS TIME

Customer #: 90380
BATES, CHARLES

Subtotal for Job #6: 0.00

W/O: 26316

Job #7 - Warranty

COMPLAINT: REFLECTOR LIGHT ON OFF DOOR SIDE OF UNIT IS A DIFFERENT STYLE LENSE

CAUSE: DIFFERENT LENSE ON THE BACK OF THE UNIT. THE LEFT TAIL LIGHT HAS SMALL CIRCLES IN A STRAIGHT LINE DOWN THE LIGHT. THE RIGHT SIDE HAS A AREA THERE IS NO LIGHTS.

CORRECTION: REPLACE RIGHT TAIL LIGHT

Subtotal for Job #7: 0.00

Parts Total: 145.78
Labour Total: 1,039.50
Sublet Total: 0.00
Extras Total: 199.01

WORK ORDER TOTAL: 1,384.29

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 17 Dec 2025



Customer #: 90380
BATES, CHARLES

