



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 26316

Customer: 90380 - BATES, CHARLES
Address: 171 ISLEY RD
BLOUNTVILLE, TN
37617
Home Phone: (423) 794-0085
Work Phone:
Author: CLP
Location: IH
Invoice #:

Stock #: 11139
Stock Desc: 2026 THFW FOREST RIVER ROGUE
351G2
Model: 351G2
Serial #: 4X4FVGL2XT5403602
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 03 OCT 25
Date In: 03 NOV 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date: 03 OCT 25

Job #WINT3 - External

COMPLAINT: WINTERIZE-FW/ CLASS A/ DESTINATION TRAILER/ DEISEL

Due to the winterization process, most refrigerator filters and water filters will need to be replaced. Because of the variability of filters, customers will be responsible for ordering/supplying the replacement filter for your unit at time of dewinterization in the spring.

Because of the number of different filters being used by manufacturers, Tri-Am RV cannot guarantee that we will have the correct filter in stock at time of the appt. Therefore, we recommend that you either pre-order your filters, or bring them with you at your appointment time.

Initial/Date: _____

CORRECTION: unit winterized

Labor

Job #	Description	Hours	Total
WINT3	WINTERIZE FRESH WATER SYSTEM	0.00	0.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #WINT3: 0.00

Job #1 - Warranty

COMPLAINT: HANDRAIL IS STRIPPED OUT

CAUSE: ALUM BRACE STRIPPED OUT AND ALLOWED HAND RAIL TO COME OFF UNIT

CORRECTION: FILL HOLES, MOVE HANDLE UP ON UNIT WHEN INSTALLING, SEAL ANY AREA NEEDED
LABOR 2.0

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: MIRROR IN KITCHEN IS CRACKED

CAUSE: MIRROR CRACKED WHILE TRAVELING

CORRECTION: REPLACE MIRROR AND FRAME

W/O: 26316

Customer #: 90380
BATES, CHARLES

LABOR 1.5

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: RUG IN TOY HAULER PART HAS A BOW IN IT

CAUSE: WHEN RUG WAS INSTALLED IT WAS NOT CUT TO FIT CORRECTLY AND IS BOWING UP ALONG THE WALL

CORRECTION: REMOVE BLACK DIAMOND PLATE ON WALL, REMOVE BOTH DOORS TO ACCESS FLOORING. CUT THE FLOORING TO FIT CORRECTLY AND REINSTALL DIAMOND PLATE AND DOORS

LABOR 3.0

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: SCUFF ON PANEL IN GARAGE PART

CAUSE: STICKER WAS REMOVED FROM FACTORY AND CUSTOMER STATED THE TOP OF THE PANEL PEELED

CORRECTION: REPLACE PANEL

LABOR 2.0

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: MASTER BEDROOM SINK IS LEAKING UNDERNEATH/ TOTE WAS FULL OF WATER

CAUSE: TECH FOUND VACUUM BREAKER IS FAULTY AND LEAKING UNDER SINK

CORRECTION: REPLACE VACUUM BREAKER AND TEST

LABOR .50

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: CHECK THAT MONITOR PANEL IS WORKING

CORRECTION: PANEL WORKS AS DESIGNED AT THIS TIME

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: REFLECTOR LIGHT ON OFF DOOR SIDE OF UNIT IS A DIFFERENT STYLE LENSE

CAUSE: DIFFERENT LENSE ON THE BACK OF THE UNIT. THE LEFT TAIL LIGHT HAS SMALL CIRCLES IN A STRAIGHT LINE DOWN THE LIGHT. THE RIGHT SIDE HAS A AREA THERE IS NO LIGHTS.

CORRECTION: REPLACE RIGHT TAIL LIGHT

LABOR .50

Subtotal for Job #7: 0.00

W/O: 26316



Customer #: 90380
BATES, CHARLES



W/O: 26316

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 20 Nov 2025

Customer Signature : _____

Customer Work
Order



Customer #: 90380
BATES, CHARLES

